

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

CLSF
Op

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

NOV 17 '89

WELL API NO.
30-015-22017

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Friendly Frenchman HB

1. Type of Well:
OIL WELL GAS WELL OTHER RECOMPLETION

8. Well No.
1

2. Name of Operator
YATES PETROLEUM CORPORATION

9. Pool name or Wildcat
Undes. Wolfcamp

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter P : 1005 Feet From The South Line and 660 Feet From The East Line
Section 32 Township 16S Range 26E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3374' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Perforate, treat Wolfcamp <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-21-89. RUPU. Unset packer and RBP. WIH to 7410' to tag cement plug. POH. Perforated Wolfcamp 5327-70' w/14 .35" holes. (Perforations-Corre. log). Set RBP at 5460' and tested to 2500#, OK. Set packer 5277'. Acidized perms w/2000 gals 20% NEFE acid, N2 and 15 ball sealers. Unset packer and TOOH.

10-25-89. Set cement retainer at 5268'. Re-cemented through perms 5327-70' w/760 sx Howco Lite w/5#/sx Salt + 150 sx Class C w/5#/sx Salt + .3% Halad-4. Did not circulate cement but did see colored water. Drilled to 5415'. Tested to 1000 psi, no bleed off.

10-28-89. Reperforated Wolfcamp 5327-5370' w/15 .42" holes as follows: 5327, 28, 29, 30, 35, 36, 37, 38, 40, 49, 50, 67, 68, 69, and 5370'. Acidized perforations 5327-70' w/2000 gals 20% NEFE acid and 50 ball sealers.

RBP @ 5463'. Packer @ 5267'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 11-14-89

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY MIKE WILLIAMS DATE DEC 11 1989

APPROVED BY SUPERVISOR, DISTRICT II TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: