

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED BY
AUG 15 1985
O. C. D.
ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO. LC 029338A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME Grayburg Jackson (SanAndres)

8. FARM OR LEASE NAME Ut. GJSAU

9. WELL NO. #33

10. FIELD AND POOL, OR WILDCAT Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 12-17S-30E

12. COUNTY OR PARISH Eddy

13. STATE N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3763' Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :		SUBSEQUENT REPORT OF :	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This injection well was shut-in by N.M. Oil Conservation Div. because 2-3/8" X 7" annulus would not hold artificially induced pressure from surface. There are no leaks from injection tubing or packer.

6/26/85: Dug 40' X 40' emergency pit. Began back flowing. Attempted to unseat packer, not successful. Ran freepoint, backed off tubing @ 2550'. 100% stuck @ 2600' (Total depth to pkr. 2827')

7/24/85: Ran overshot and jars;

7/25/85: Jarred on fish 10 hrs.

7/26/85: Jarred on fish 10 hrs.

7/29/85: Jarred on fish 4 hrs., trip for new grapple.

7/30/85: Jarred on fish 2 hrs., recovered 32' 2-3/8" tubing (broke off)

7/31/85: Jarred on fish 10 hrs.

8/1/85: POOH, Jarring not successful. Now polling WIO's for determination to P&A. Doubtful if pipe recovery and well repair costs justify continuing operations.

18. I hereby certify that the foregoing is true and correct

SIGNED John C. McPhaul TITLE PRODUCTION SUPERINTENDENT DATE 8/6/85

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

AUG 13 1985

*See Instructions on Reverse Side