

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1001-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO. **437**
NM 54184
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Dunn B
9. WELL NO.
31
10. FIELD AND POOL, OR WILDCAT
Artesia (O, Gbr, SA)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 11-18-28
12. COUNTY OR PARISH
Eddy
13. STATE
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED BY
MAR 23 1987
OCS
ARTEZIA OFFICE

1. OIL WELL GAS WELL OTHER
2. NAME OF OPERATOR
DEPCO, Inc.
3. ADDRESS OF OPERATOR
800 Central, Odessa, Texas 79761
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface B-660' FNL & 1980' FEL, Sec 11, T-18S, R-28E

14. PERMIT NO. 3646 DF 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)
PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)
REPAIRING WELL
ALTERING CASING
ABANDONMENT*
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 2-3-87: Set CIBP @ 2520' w/35' cmt on top. Pumped 10# mud from top of plug to sfs. Had found hole in 4 1/2" csg @ 525' on 2-2-87. Called Vince Balderaz for approval to pump cmt thru it. Pumped 200 sx cmt thru hole @ 525' & circ to surface. Cmt in pipe inside & out from 525' to sfs.
- 2-4-87: Set dry hole marker, filled pit & cleaned location.



18. I hereby certify that the foregoing is true and correct
SIGNED *R. L. Denney* R. L. Denney TITLE Chief Production Clerk DATE 2-11-87

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 3-19-87

CONDITIONS OF APPROVAL, IF ANY:

Post ID-2
2-10-27
P+R

*See Instructions on Reverse Side