

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED
MAY 27 1983
O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
V-689

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER
2. Name of Operator
Harvey E. Yates Company ✓
3. Address of Operator
P. O. Box 1933, Roswell, New Mexico 88201
4. Location of Well
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 6 TOWNSHIP 19S RANGE 29E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
3393.4' GL

7. Unit Agreement Name
8. Farm or Lease Name
SST
9. Well No.
1
10. Field and Pool, or Wildcat
Wildcat-Bone Springs
12. County
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING OTHER
SUBSEQUENT REPORT OF:
REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOB
OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
5/13/83 GIH w/2 3/8" tbg to 7880' w/pkr @ 7786' & SN @ 7938'. Acidize w/500 gals 15% HCL & 2300#.
5/14/83 Acidize w/3000 gals 20% spearhead @ 1900#.
5/17/83 Acidize w/6000 gal 28% Spearhead. Dropped 40 rubber coated ball sealers, perfs balled off w/32 ballsealers on form.
5/20/83 RU Western & Acid w/5000 gal 28% & 5000 gal 15%.
5/22/83 Start running rods. Ran 190 3/4" rods, 123 7/8" rods, 1-8' pony rod, 1-2' pony rod 2-6' pony rod, GIH w/2"X1-1/4"X20' pump, 1-25' polish rod to 7938'. Well put on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNED Ray T. D. [Signature] TITLE Reservoir Engineer DATE May 26, 1983
APPROVED BY _____ ORIGINAL SIGNED BY Leslie A. Clements
TITLE Supervisor District II DATE MAY 31 1983
CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input type="checkbox"/>
LAND OFFICE	<input type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

MAY 16 1983

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
V-689

7. Unit Agreement Name

8. Farm or Lease Name
SST

9. Well No.
1

10. Field and Pool, or Wildcat
Wildcat-Bone Springs

12. County
Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER

2. Name of Operator
Harvey E. Yates Company ✓

3. Address of Operator
P. O. Box 1933, Roswell, New Mexico 88201

4. Location of Well
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 6 TOWNSHIP 19S RANGE 29E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3393' 4GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
SUBSEQUENT REPORT OF:

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER _____

PLUG AND ABANDON

CHANGE PLANS

OTHER _____

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

OTHER _____

ALTERING CASING

PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4/12/83 MI & RU Monument, PU & Rev Unit. Drill out surface plug & Cmt plug @ 315'. Circ well clean to pit to 1980'.
- 4/13/83 Tag cmt plug @ 2875'. Drill to 5 1/2" csg stub @ 2911'.
- 4/14/83 Work skirt over csg stub & Mill over csg. GIH w/Impression Block, block showed good stub.
- 4/15/83 Set slips & cut off csg. Ran 70 jts of 5 1/2" ST&C, K-55 csg. Csg patch and corrected depth of 2894'. Max press on patch not to exceed 3500#.
- 4/18/83 Drill & push CIBP to 3661'. Drill 230' w/cmt plug, GIH to 8464'.
- 4/20/83 RU Geosource & cmt bond, GR & csg collar log to 8474 up to 2800'. Come off of cmt @ 3400'.
- 4/21/83 Perf from 8240' to 8248', 2 spf. Hung tbg on @ 8226'.
- 4/27/83 Sqz perfs - 8240-8248.
- 4/29/83 Perf from 8424' to 8246', total 10 holes.
- 5/06/83 Acidize w/3000 gals 5% HCL, 6 gals 115, 12 gals LT-17, 9 gals XD 26, 15 gals CS3, 60 gals SC-100, 1200# AB54.
- 5/10/83 Frac 19,000 gals 3% acid, 1100 gals CO2, 30,000# 20/40 sand, pmpd 18 BPM @ 4600.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray J. [Signature] TITLE Reservoir Engineer DATE May 12, 1983

APPROVED BY _____ TITLE Supervisor District II DATE MAY 16 1983