

Memo

From

W. A. GRESSETT
Supervisor

To Mr. Ramey

Do you see any problems with this.

2/26

Amoco Wood #10

L 27-18-31

Deviation summary

Bill -

They sure did have a lot of deviation

but are within the production limit. Drift probably wasn't all in one direction. Looks OK to me.