

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

RECEIVED

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

SEP 08 1992

O. C. D.  
OFFICE

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
30-015-24141

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

1. Type of Well:  
OIL WELL  GAS WELL  OTHER Dry Hole

Genecco Com 14D

2. Name of Operator  
Nearburg Producing Company

8. Well No.  
1

3. Address of Operator  
P. O. Box 823085, Dallas, Texas 75382-3085

9. Pool name or Wildcat  
Cemetery Morrow

4. Well Location  
Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line  
Section 14 Township 20S Range 25E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3,415.9' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/27/92 Mix and pump 25 sx Class H cement plug from 9,500' - 9,122'.  
7/28/92 Tag cement plug at 9,103'. Mix, pump, and lay 25 sx cement plug from 8,800' - 8,422'.  
7/29/92 Pump 12 sx cement plug from 7,610' - 7,460'. Set retainer at 6,805'. Pump 30 sx Class H cement plug, left 70' cement on top of retainer.  
7/30/92 Set 200 sx cement plug from 2,840' - 2,100' per Mike Williams (NMOCD District II Office).  
7/31/92 Tag cement plug at 2,450'. Spot 30 sx cement plug from 1,425' - 1,325'. WOC 2 hours and tag at 1,350'. Set an additional 10 sx cement plug at 1,350'. Set 30 sx cement plug from 950' - 850'. Set 30 sx cement plug from 402' - 302'. Set 10 sx cement surface plug. Set dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mildred Simpkins TITLE Production Analyst DATE 9/4/92  
TYPE OR PRINT NAME Mildred Simpkins TELEPHONE NO. 214/739-1778

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: