FOR INFORMATION ONLY

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bure	eau No. 10	004-0135
Expires:	March 31	1993

SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Serial No.
		NM-56220
	drill or to deepen or reentry to a different reservoir.	6. If Indian, Alottee or Tribe Name
Use "APPLICATION F	OR PERMIT for such proposals	A STATE OF THE STA
SUBM	IT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
		8. Well Name and Number
1. Type of Well: ☐ OIL ☐ GAS ☐ WELL ☐ WELL ☐	OTHER	DD 24 FEDERAL
2. Name of Operator TEXACO EXPLORA	ATION & PRODUCTION COME COME	3
3. Address and Telephone No. P.O. BOX 730, HOL	BBS, NM 88240 397-0418	9. API Well No. 30-015-27212
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description)	10. Field and Pool, Exploratory Area
	ne SOUTH Line and 1650 Feet From The	WILDCAT CANYON WOLFCAMP NORTH
EAST Line Section 24	Township 19-S Range 24-E	11. County or Parish, State EDDY , NEW MEXICO
12. Check Appropriate	Box(s) To Indicate Nature of Notice, Re	eport, or Other Data
	T	YPE OF ACTION
TYPE OF SUBMISSION		Change of Plans
	Abandonment	New Construction
	Recompletion	
Notice of Intent		Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
Final Abandonment Notice	OTHER:	☐ Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
Describe Proposed or Completed Operations (Clear directionally drilled, give subsurface locations and recognitions)	urty state all pertinent details, and give pertinent dates, including neasured and true vertical depths for all markers and zones pe	g estimated date of starting any proposed work. If well is entinent to this work.,)*.
PRIOR TO THIS PROPOSAL TO RECOMPLE DAGGER DRAW UPPER PENN NORTH POO	TE TO THE WILDCAT CANYON WOLFCAMP NORTH L.	I POOL, THIS WELL PRODUCED FROM THE
1. MIRU. Install BOP. TOH w/ production equi	oment.	
2. TIH w/ CIBP to ~7200'. Set CIBP. Spot 35' C	mt Cap. (NEW PBTD @ 7165')	
3. Run GR-CBL from PBTD to FL or TOC.		
4. Install 5000 psi Lubricator. Perf Upper Wolfd	amp w/ 4 SPF from 6218'-6542' (61' NET , 244 holes).	
5. TIH w/ treating pkr on 2-7/8" WS & set pkr @	6150'.	

14. I hereby certify that the foregoing is true and SIGNATURE	TITLE Engr Asst	DATE	2/6/96
TYPE OR PRINT NAME	Monte C. Duncan		
(This space for Federal or State office use)			
APPROVED BY	TITLE	DATE	
CONDITIONS OF APPROVAL, IF A	NY:		
	grime for any person knowingly and willfully to make to any department or agency of the Un	ited States any false, fictitious or fraudulent statem	ents or

representations as to any matter within its jurisdiction.

6. Load annulus w/ 2% KCI. Acidize perfs w/ 4200 gals of 15% HCL NEFE. Overflush with 50 Bbls 2% KCL water.

Max pressure 5000 psig on tubing. SI for 2 hr. Swab back load.

7. Release & TOH w/ pkr on WS. TIH w/ production equipment & return well to production.