

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

CISF  
4

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015- <u>31103</u>
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator OXY USA Inc. 16696		6. State Oil & Gas Lease No. <u>105056</u>
3. Address of Operator P.O. BOX 50250 MIDLAND, TX 79710-0250		7. Lease Name or Unit Agreement Name: <u>OXY Crendelan State</u>
4. Well Location Unit Letter <u>D</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>20</u> Township <u>19S</u> Range <u>28E</u> NMPM EDDY County		8. Well No. <u>1</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3509'</u>		9. Pool name or Wildcat <u>South Millman Morrow</u>
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>		<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> OTHER: <input type="checkbox"/>
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		

See other side



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE REGULATORY ANALYST DATE 6/2/00

Type or print name DAVID STEWART Telephone No. 915-685-5717  
(This space for State use) Jim W. Gunn

APPROVED BY Jim W. Gunn TITLE SUPERVISOR, DISTRICT II DATE JUN 08 2000  
Conditions of approval, if any:

ATTACHMENT C-103

OXY USA INC.

OXY CRENDELAU STATE #1

SEC 20 T19S R28E

EDDY COUNTY, NM

NOTIFIED NMOCD 5/19/00, MIRU UTI #308, SPUD WELL @ 2300hrs MDT 5/19/00. DRILL 17-1/2" HOLE DRILL TO TD @ 430', 5/19/00. RIH W/ 13-3/8" 48# H40 CSG & SET @ 430'. M&P 160sx 35:65 POZ/C W/ 6% BENTONITE + 2% CaCl<sub>2</sub> + .5#/sx CELLOFLAKES FOLLOWED BY 200sx CL C W/ 2% CaCl<sub>2</sub>, DISP W/ FW, PLUG DOWN @ 0920hrs MDT 5/20/00, CIRCULATE 67sx CMT TO PIT, WOC-5hrs. NMOCD NOTIFIED, BUT DID NOT WITNESS. CUT OFF CASING, WELD ON STARTING HEAD, TEST TO 500#, OK. NU BOP & CHOKE MANIFOLD, TIH W/ BIT & BHA, TEST CASING & HYDRIL TO 500#, OK. TOTAL WOC-18hrs. RIH & TAG, DRILL OUT & DRILL AHEAD 5/21/00.

DRILL 12-1/4" HOLE TO TD @ 3000', 5/24/00, CHC. RIH W/ 9-5/8" 36# CSG & SET @ 3000'. M&P 870sx 35/65 POZ/C W/ 6% BENTONITE + 1% CaCl<sub>2</sub> + 5#/sx GILSONITE FOLLOWED BY 200sx CL C CMT W/ 2% CaCl<sub>2</sub>, DISP W/ FW, PLUG DOWN 5/25/00, CIRCULATED 312sx TO PIT, WOC-8hrs. CUT OFF CSG & INSTALL B SEC, TEST TO 2000#, OK. NU BOP, TEST TO 5000#, OK. TEST CSG & MUD LINE TO 2500#, ANNULAR TO 3000#. OK. RIH, DO CMT & SHOE, DRILL NEW FORMATION, TEST CSG, OK. NMOCD NOTIFIED OF CSG/CMT JOB BUT DID NOT WITNESS. DRILL AHEAD 5/26/00.