

clst
DP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO 30-015-23370 20761
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Dinero Exxon Pardue Farms	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Dinero Operating Company ✓		8. Well No. 2
3. Address of Operator P.O. Box 10505, Midland, Texas 79702		9. Pool name or Wildcat Catclaw Draw (Delaware)	
4. Well Location Unit Letter <u>G</u> : <u>1942</u> Feet From The <u>North</u> Line and <u>1525</u> Feet From The <u>East</u> Line Section <u>22</u> Township <u>215</u> Range <u>25E</u> NMPM <u>Eddy</u> County			
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3465 GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>Open additional section - Delaware</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-26-91 - Rigged up and pulled rods and tubing out of well. Go in with casing gun and perforated 2,920 to 2,930, 2,962-2,978'. Acidize with 5,000 gallons acid and put will back on production - 3-28-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charlie Williams TITLE Production Superintendent DATE 4-18-91

TYPE OR PRINT NAME Charlie Williams TELEPHONE NO. 915 684-5544

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE **APR 23 1991**

CONDITIONS OF APPROVAL, IF ANY: