


REQUIRED DEVELOPMENT PLAN FOR SURFACE USE

1. See attached Item 1.
2. See attached Item 2.
3. See attached Item 3.
4. See attached Item 4.
5. Tank Batteries and Flow Lines: Producing facilities will be located on the location pad in the event production is established.
6. Water Supply: Fresh water for the drilling operations will be purchased and hauled to location from Carlsbad, N. M.
7. Methods for Handling Waste Disposal: All waste material developing during drilling operations will be buried at the location. Drill cuttings will be covered in the reserve mud pit. All garbage, trash and junk will be buried in a separate earthen pit.
8. None.
9. None.
10. See attached Item 10.
11. Location will be restored to its natural grade and contour and reseeded as required.
12. The area is rough and barren of vegetation. The location is on a bluff approximately 1/2 mile south of the Pecos River Valley.



Jim L. Sharp, Field Representative
Hobbs, New Mexico
Phone: 505-393-4111