

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	✓

Form C-103
Supersedes Old
C-102 and C-103
Effective 10-65

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

OCT 31 1975

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Harvey E. Yates Company, Inc. ✓		5. State Oil & Gas Lease No. OG-6027
3. Address of Operator Suite 1000, Sec. Nat'l Bank Bldg., Roswell, NM		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>G</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> SIDE, SECTION <u>15</u> TOWNSHIP <u>21S</u> RANGE <u>27E</u>		8. Form or Lease Name Cedar Hills Unit
15. Elevation (Show whether DF, RT, GR, etc.)		9. Well No. #2
		10. Field and Pool Name Und Burton Flat Strawn-Morrow
		11. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
REEL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <u>Completion Work</u>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and finishing work) SEE RULE 1103.

Perforated Strawn as follows:
Perforated 10,411 to 10,417 4 shots
10,424 to 10,430 4 shots
10,439 to 10,441 4 shots

Acid Treatments: Perfs 10,411 to 441 KB 150 gals 10% acetic acid.
Perfs 10,411 to 441 KB 2500 gals 15% DS-30 w/1000 2% KCL WATER

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harvey E. Yates TITLE Vice President DATE 10/30/75

APPROVED BY W.A. Swant TITLE SUPERVISOR, DISTRICT II DATE NOV 10 1975

CONDITIONS OF APPROVAL, IF ANY: