

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

FEB - 7 '90

WELL API NO.

30-015-23301

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Eddy "C" State

8. Well No. 1

9. Pool name or Wildcat
Indian Flats

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Chevron U.S.A. Inc.

3. Address of Operator

P.O. Box 670, Hobbs, NM 88240

4. Well Location

Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line

Section 2 Township 22S Range 38E 28 NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SET 4" CICR @ 9550 ± (TOP OF WOLFCAMP @ 9610') SQZ LOWER WOLFCAMP PERFS 9834-9855 W/50 SXS CLASS C CMT & CAP CICR W/30' CMT, SPOT P&A MUD, SET 200' BALANCED CMT PLUG F 8665 TO 8465' W/7510 TO 7310' W/25 SXS CMT TO COVER 5 1/2" CSG TOP OF CMT @ 7410, FREEPOINT 5 1/2" CSG AND CHEMICAL CUT 5 1/2" CSG AS CLOSE TO CMT PLUG @ 7310' AS POSSIBLE, PER FPI RESULTS, TOH LAYING DN 5 1/2" CSG & INSTALLING THREAD PROTECTORS, TIH W/OE TBG SPOT 100' CMT PLUG ACROSS TOP OF 5 1/2" CSG STUB, CIRCULATE WELLBORE W/P&A MUD, SPOT 200' BALANCED CMT PLUG F 6300 TO 6100 W/50 SXS CMT TO COVER TOP OF BONE SPRINGS @ 6200', SPOT 200' BALANCED CMT PLUG F 3800' TO 3600' W/50 SXS ACROSS 8 5/8" CSG SHOE @ 3706', SPOT 200' BALANCED CMT PLUG F 2700' TO 2500' W/50 SXS ACROSS BASE OF SALT, SPOT 200' BALANCED CMT PLUG F 550 TO 350 W/50 SXS ACROSS TOP OF SALT & 11 3/4" CSG SHOE, SET 60' CMT PLUG F 60' TO SURFACE W/15 SXS AS A SURFACE PLUG, CUTOFF WELLHEAD & ANCHORS 3' BELOW GROUND LEVEL, INSTALL DRYHOLE MARKER & CHANGE WELL STATUS TO PLUGGED AND ABANDONED.

** SEE ATTACHED FOR FORMATION TOPS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akins 2/5/90 TITLE Staff Drlg. Engr.

DATE 2-5-90

TYPE OR PRINT NAME M.E. Akins

TELEPHONE NO. 393-4121

(This space for State Use)

APPROVED BY Danell Moore TITLE

DATE 3/28/90

CONDITIONS OF APPROVAL, IF ANY:

Convert to cgs @ 1100

EDDY "C" STATE #1
FORMATION TOPS:

TOP/SALT	550
BASE/SALT	2650
TOP/YATES	2650
TOP/BONE SPRINGS	6200
TOP/WOLFCAMP	9610
CANYON	10890
STRAWN	11050
ATOKA	11390
MISS	12614