- 80,44	STARESENED D
DEPARTMEN	OF THE INTERIOR AL SORVEY 198
GEOLOGIĆ	AL SORVEY D 130

UNITED STATESEIVED BY	5. Lr ·SE
AF THE INTERIOR	N. 42207
GEOLOGICAL SORVEY 3 1304	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
O. C. D. SUNDRY NOTICES AND REPORTS OF LEWELLS	7. UNIT AGREEMENT NAME
(No not use this form for proposals to draw in despen or prug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
and the second s	Washington Ranch Storage Project
1. oil [] gas well other Gas Storage	9. WELL NO. 4
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
El Paso Natural Gas Co.	Washington Ranch Morrow
3. ADDRESS OF OPERATOR 1800 Wilco Bldg., Midland, Tx 79701	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below)	Sec. 34, T-25-S, R-24-E
AT SURFACE: 2736' FSL & 1602' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Eddy N. Mex
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) GR 3715'
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF [_] [.]	
SHOOT OR ACIDIZE	
REPAIR WELL [] [X]	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
PULL OR ALTER CASING [ ] [ ]  MULTIPLE COMPLETE [ ]	•
CHANGE ZONES	
ABANDON • LJ LJ other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent	ectionally drilled, give subsurface locations and
1.) Set tubing plug. RU and install 50	00 psi hydraulic BOP.
2 ) Rig up Shubbing unit, pull and lay down 2 7/8" production tubing.	
3.) RU wireline unit and set Baker Model FA-1 permanent packer at 0000	
wlm, with blanking plug below packe	r. wro took to 3000 hsig
4.) Load 7" casing with water and pressure test to 3000 psig. 5.) Run $4\frac{1}{2}$ " 11.6# K-55 tubing with Baker K-22 latch in seal assembly,	
5.) Run $4\frac{1}{2}$ " 11.6# K-55 tubing with Bake circulate inhibited packer fluid, 1	atch into packer.
6.) Nipple down BOP, Nipple up wellhead	
7.) Pressure test tubing to 3000 psig.	Retrieve Blanking Plug,
return to service.	
ubsurface Safety Valve: Manu. and Type	Ft.
8. I hereby certify that the foregoing is true and correct	
ACCEPTED FOR RECORDs space for Federal or State office	DATE 9-10-84
PPROVED BY	DATE
SEP 1 2 1984	·

aclalad, NEW MEXICO \*See Instructions on Reverse Side