

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30015 29309
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name HARROUN 15
8. Well Number 4
9. OGRID Number 017891
10. Pool name or Wildcat Cedar Canyon Del & E. Pierce Crossing BS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

RECEIVED

MAR 15 2004

OCD-ARTESIA

2. Name of Operator
Pogo Producing Company

3. Address of Operator
P O Box 10340; Midland, Tx 79702-7340

4. Well Location

Unit Letter I : 2260 feet from the South line and 330 feet from the East line

Section 15 Township 24S Range 29E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
2930' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: DO CIBP & COMMINGLE BS & DEL ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06-24-03 POOH w/ rods & pump
06-25-03 Perf Delaware @ 5114-26' w/ 2 spf. RIH w/ RBP & set @ 5248'. Test to 3000# ok. Acidize w/ 1000 gals 7.5 % acid. Swab well.
06-27-03 Perf Delaware @ 4858-66' w/ 2 spf. Rel RBP @ 5248' & set @ 5065', test to 3000# ok.
06-28-03 Acidize w/ 1000 gals 7.5% acid.
07-01-03 Rel RBP @ 5065' & set @ 4297', test to 3000# ok. Perf Delaware @ 3822-38 w/ 2 spf.
07-02-03 Acidize w/ 1200 gals 7.5% acid.
07-03-03 Rel RBP @ 4297' and POOH. Bail sd to CIBP @ 6800'.
07-04-03 DO CIBP @ 6800' & POOH. Commingle Bone Spring and Delaware.
07-17-03 Test: 52 BO, 81 BW, 116 MCF.

DHC Order: DHC 3156

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathern TITLE Sr. Production Analyst DATE 3-12-04

Type or print name Terri Stathern E-mail address: Telephone No. 432-685-8100

(This space for State use)

FOR RECORDS ONLY

APPROVED BY _____ TITLE _____ DATE MAR 21 2004

Conditions of approval, if any: