

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR 26 2004

OCD-ARTESIA Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141  
Revised October 10, 2003

30-015-20300

Release Notification and Corrective Action

090504089285

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Co., LP	Contact: Jennifer Van Curen
Address: PO Box 250; Artesia, NM 88211	Telephone No. 505-748-0160
Facility Name Littlefield AB Federal Unit G #11	Facility Type Well

Surface Owner	Mineral Owner	Lease No. NM 014103
---------------	---------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	22	18S	31E	1980	North	1980	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: Water	Volume of Release: 50 bbls	Volume Recovered: 0 bbls
Source of Release: Water injection line	Date and Hour of Occurrence: 3-20-04: 11:30 AM	Date and Hour of Discovery: 3-20-04: 11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Van Barton-OCD	
By Whom? David Sherrell; Lease Operator	Date and Hour: 3-20-04; 12:36 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A hole in collar washed out in the injection line located in the Littlefield AB Federal lease. The pump was shut down and line was isolated. Repaired line with plastic coated pipe. Replaced the Murphy switch that should have shut down the pump.

Describe Area Affected and Cleanup Action Taken.\*

The area affected was a 40' X 20' area in pasture made up of mostly sand. 0 bbls of water was recovered due to the porosity of the sand. The area was tilled and fertilizer was added for remedial purpose. Will continue to rake area and check for necessity of further action.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Van Curen</i>	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Van Curen	Approved by District Supervisor:	
Title: Production Field Tech	Approval Date:	Expiration Date:
E-mail Address: Jennifer.Vancuren@dm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/24/04	Phone: 748-0160	

\* Attach Additional Sheets If Necessary

\* Faxed 6/24/04.

\* In good.