N.M. Oil Cons. DIV-Dist. 2 1301 W. Grand Avenue

Form 3160-5 (September 2001)

Artesia, NM 88210 UNITED STATES

DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0135

BUREAU OF LAND MANAGEMENT 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NM 030752 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUPPORT NUTRIPLICATIES Other his most ions conjecterse side SRM - 1406 Type of Well Well Name and No. Oil Well Gas Well Other TRIGG-JENNING. COM #1 2. Name of Operator E.G.L. RESOURCES, INC. API Well No. 30-015-22784 3a, Address 3b. Phone No. (include area code) (432) 687-6560 P.O. BOX 10886 MIDLAND, TX 10. Field and Pool, or Exploratory Area RECEIVED TURKEY TRACK MORROW NORTH (GAS) Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 660' FSL & 1980' FWL MAR 1 7 2004 UNIT N. SEC. 28, T18S, R29E EDDY COUNTY, NEW MEXICO 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Reclamation Well Integrity Fracture Treat Casing Repair New Construction Recomplete Other ☐ Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Plug Back Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1. MIRU workover unit. ND wellhead. NU BOP. POOH tallying tubing. 2. RIH w/ CIBP and set at 10,950'. Dump bail 35' cement on top of CIBP. 3. Perforate Atoka formation from 10,548' to 10,640'. Run pkr. Acidize and swab test zone for commercial production. Plugback w/ CIBP and cement if necessary. Perforate Strawn formation from 10,242' and 10,268'. Run pkr. Acidize and swab test zone for commercial production. Plugback w/ CIBP and cement if necessary. Perforate Canyon formation from 9,886' to 9.910'. Run pkr. Acidize and swab test zone for

7. Run 2-3/8" tubing.8. ND BOP. NU wellhead. RD workover unit.	Clean location.	APPROVED
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) JESSICA LOPEZ	Title TECHNICAL ASSIS	MAR 1 6 2004
Signature Signature Which	Date MARCH 5, 2004	LES BABYAK
NIHIS SPACEUROR PEDERA	L'OR STATIE OFFICE USE	
Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warre certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	nt or lease Office	

Perforate Wolfcamp formation from 9,222' to 9,244'. Run pkr. Acidize and swab test zone for

commercial production. Plugback w/ CIBP and cement if necessary.

commercial production.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.