

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTBudget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals.)

| | | | | | |
|---|--|--|--|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | RECEIVED | | 5. LEASE DESIGNATION AND SERIAL NO. LC-029419-A | |
| 2. NAME OF OPERATOR The Wiser Oil Company | | JUL 16 2004 | | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | |
| 3. ADDRESS OF OPERATOR P. O. Box 2568 Hobbs, New Mexico 88241 | | OCC. ARTESIA | | 7. UNIT AGREEMENT NAME Skelly Unit | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1310' FSL & 1310' FEL Unit P | | | | 8. API WELL NO. 30-015-25040 | |
| | | | | 9. WELL NO. 158 | |
| | | | | 10. FIELD AND POOL, OR WI Grayburg Jackson Fren 7 Rivers QN GB SA | |
| | | | | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22-T17S-R31E | |
| 14. PERMIT NO | | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3837' GR | | 12. COUNTY OR PARISH Eddy | |
| | | | | 13. STATE NM | |

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| TEST WATER SHUT OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/> | MULTIPLE COMPLETE <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/> | ABANDON* <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |

(Other) Remedial Workover

SUBSEQUENT REPORT OF:

| | |
|--|--|
| WATER SHUT-OFF <input type="checkbox"/> | REPAIRING WELL <input type="checkbox"/> |
| FRACTURE TREATMENT <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT * <input type="checkbox"/> |
| (Other) <input type="checkbox"/> | |

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)
IN REPLY REFER TO: 3162 (080)04-DW-046L
NMLC029419A

Perfs: 2201'-2422'

1. MIRU. TIH w/drilling bailer to 2156' and tag CIBP.
2. Push CIBP to 3200'.
3. LD drilling bailer.
4. TIH w/tbg. to 2450'. Circulate hole clean.
5. Spot 750 gals. 15% NE-FE anti-sludge acid across perfs.
6. Put acid away. S.I. overnight.
7. Place well on pump. Return well to production.
8. RDMO.

Note: Date for work to start will be May 10, 2004. Anticipate return to production when completed.

18. I hereby certify that the foregoing is true and correct.

SIGNED [Signature] TITLE Production Superintendent DATE May 5, 2004

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) ALEXIS C. SWOBODA
CONDITIONS OF APPROVAL, IF ANY:TITLE PETROLEUM ENGINEER DATE JUL 14 2004

*See Instruction On Reverse Side