



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

Lori Wrotenbery
Director

Oil Conservation Division

23 April 2003

HARVEY E YATES CO
PO BOX 1933
ROSWELL, NEW MEXICO 88202



7-16-04
P/A - RELEASE
/s/

Form C-103 Report of Plugging for your Loco Hills Welch # 5 L-4-18-26 API 30-015-31232 -
Cannot be approved until an NMOCDD representative has made an inspection of the location and found it to
be cleared to comply with OCD rules and regulations. Please check each item in the space provided to
indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Joanna Prukop
Name

Cabinet Secretary
Title

Van Barton
Field Rep. II


Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-015-31232
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. Fee lease
7. Lease Name or Unit Agreement Name: LOCO HILLS WELCH
8. Well No. 5
9. Pool name or Wildcat LOCO HILLS BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Harvey E. Yates Company	
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88202	
4. Well Location Unit Letter <u>L</u> : <u>1450</u> feet from the <u>SOUTH</u> line and <u>660</u> feet from the <u>WEST</u> line Section <u>4</u> Township <u>18 S</u> Range <u>29 E</u> NMPM <u>EDDY</u> County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3540' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: ADD PERFORATIONS <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

03/15/2003 DAY 01, MI RU SMITH & MARRS. ND WH & NU BOP. POOH W/196 JTS 2 3/8" TBG. GIH W/5 1/2" CIBP & SET @ 6300'. GIH W/TBG & SET 50' CMT ON TOP OF CIBP. LOAD HOLE W/9# MUD. PULL UP TO 4120', SPOT 25 SX CMT. PU TO 3136', SPOT 25 SX CMT PLUG. WOC. POOH W/TBG.

03/18/2003 DAY 02, GIH W/TBG & TAG TOC AT 2822'. WELD ON CSG STUB ON TO 5 1/2" CSG. GIH W/WIRE LINE. CUT CSG AT 1452'. LAY DOWN 13 JTS 5 1/2" CSG.

03/19/2003 DAY 03, FINISH PULLING OUT OF HOLE W/5 1/2" N-80 CSG. LD 32 JTS TOTAL. TIH W/TBG TO 1504' & SPOT 35 SX CMT. WOC. GIH & TAG TOP OF PLUG AT 1352'. PULLED UP TO 864' AND SPOT 35 SX CMT. WOC. GIH & TAG TOP OF PLUG @ 738'. PULL UP TO 450'. SPOT 35 SX CMT. WOC.

03/20/2003 DAY 04, GIH W/TBG. TAG TOP OF PLUG @ 321'. PULL UP & SPOT 20 SX CMT FOR SURFACE PLUG. INSTALL DRY HOLE MARKER. RD & CLEAN LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeanetta Atkinson TITLE Production Analyst DATE 4/21/03

Type or print name Jeanetta Atkinson Telephone No. 505-623-6601
(This space for State use)

APPROVED BY [Signature] TITLE Wild Dog DATE JUL 16 2004
Conditions of approval, if any: