13160-5 13160-5 19999 02 DEPARTMENT OF THE	Oil (	Cons.			
UNITED STATE	ALAA DI	V-Dist. 2		FORM APPROVED	<
		rand Ave	nue	OMB No. 1004- 0135	•
BUREAU OF LAND MAN	AGEMENT	VM 8821	∩ ∟	Expires: November 30, 2000	)
BUREAU OF LAND MAY BUREAU OF LAND MAY RECEIVER BUNDRY NOTICES AND REPO Do not use this form for proposals to d abandoned well. Use Form 3160-3 (APL	DRTS ON W	ELLS	5. Lease Se NM-158		
P Rt AK Do not use this form for proposals to d	rill or to re-ente	er an	6. If Indian	a, Allottee, or Tribe Name	
abandöned well. Use Form 3160-3 (APL			7 If Unit o	r CA. Agreement Designation	
	s an reverse	And Transferrer		A CA. Agreement Designation	L
1. Type of Well					
Oil Well X Gas Well Other AMEN	DED		8. Well Na	me and No.	
2. Name of Operator				ood Federal #5	
Yates Petroleum Corporation / 3a. Address 33b.	Phone No. (includ	le area code)	9. API Wel 30-005-6		
	505) 748-147	-		nd Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Pecos Sl	ope Abo/Wildcat We	olfcamp
1980'FSL & 1980'FEL of Section 26-T6S-R25E	T			or Parish, State	
				County, New Mexico	)
12. CHECK APPROPRIATE BOX(S) TO INDICATE NA				DATA	
TYPE OF SUBMISSION	T	YPE OF ACTIO	N		
Notice of Intent Acidize De	æpen	Production ( St	art/ Resume)	Water Shut-off	
Altering Casing	acture Treat	Reclamation		Well Integrity	
X Subsequent Report Casing Repair Ne	w Construction	Recomplete		X Other Workov	ver
	ig and abandon	Temporarily A	bandon	AMEN	DED
	-				
Final Abandonment Notice     Convert to Injection   Phi	ng hack	Water Disposa	1		
Final Abandonment Notice Convert to Injection Plu 13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)	locations and meas le with the BLM/ B completion or reco	sured and true vertica BIA. Required subseq completion in a new in	d work and approxi l depths or pertinent uent reports shall be terval, a Form 3160	t markers and sands. e filed within 30 days )-4 shall be filed once	
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fillowing completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing.</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi	g date of any propose sured and true vertica BIA. Required subseq completion in a new in ing reclamantion, hav	d work and approxi l depths or pertinen uent reports shall b terval, a Form 3160 e been completed, a	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has	cid on
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav	d work and approxi l depths or pertinen juent reports shall be terval, a Form 3160 e been completed, a Milled on plug	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted at	cid on
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with mill and coiled tubing. Tagged plug at the site is ready plug at the site is maintained.</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800	g date of any propose sured and true vertica BIA. Required subseq completion in a new in ing reclamantion, hav blug at 4800'. ]	ed work and approxi d depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug	t markers and sands. e filed within 30 days >4 shall be filed once and the operator has g 8 hours. Spotted at g for 5 hours.	
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with mill and coiled tubing. Tagged plug a 10/18-20/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 1 BK in hole	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. 1 '. Milled on co with underrean	ed work and approxi l depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk b	t markers and sands. e filed within 30 days >4 shall be filed once and the operator has g 8 hours. Spotted at g for 5 hours.	
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with mill and coiled tubing. Tagged plug a 10/18-20/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. ] '. Milled on co with underrean onset packer and	ed work and approxi l depths or pertinen uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk b I POOH.	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. pasket. Tagged up 2-	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all read determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur ed out to 520	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. ] '. Milled on co with underrean onset packer and	ed work and approxi l depths or pertinen uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk b I POOH.	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. pasket. Tagged up 2-	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with mill and coiled tubing. Tagged plug a 10/18-20/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur ed out to 520	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. ] '. Milled on co with underrean onset packer and	ed work and approxi l depths or pertinen uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk b I POOH.	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. pasket. Tagged up 2-	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all read determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur ed out to 520 led up tree.	g date of any propose sured and true vertica BIA. Required subseq completion in a new in ing reclamantion, hav olug at 4800'. I '. Milled on co with underrean onset packer and 00'. TIH with 5	ed work and approxi l depths or pertinent uent reports shall bu- terval, a Form 3160 e been completed, a Milled on plug pomposite plug ner and junk b I POOH. 5-1/2 ASI pacl	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. pasket. Tagged up 2-	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur ed out to 520 led up tree.	g date of any propose sured and true vertica BIA. Required subseq completion in a new in ing reclamantion, hav olug at 4800'. I '. Milled on co with underrean onset packer and 00'. TIH with 5	ed work and approxi l depths or pertinent uent reports shall bu- terval, a Form 3160 e been completed, a Milled on plug pomposite plug ner and junk b I POOH. 5-1/2 ASI pacl	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. pasket. Tagged up 2- ker and 1.87" on/off	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fillowing completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with mill and coiled tubing. Tagged plug at 10/18-20/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur ed out to 520 led up tree.	g date of any propose sured and true vertica BIA. Required subseq completion in a new in ing reclamantion, hav olug at 4800'. I '. Milled on co with underrean onset packer and 00'. TIH with 5	ed work and approxi l depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk b I POOH. 5-1/2 ASI pacl CCEPTED	t markers and sands. e filed within 30 days >4 shall be filed once and the operator has g 8 hours. Spotted an g for 5 hours. basket. Tagged up 2- ker and 1.87" on/off	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order E Pecos Slope Abo Oil - 0% Gas - 83.33%</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur ed out to 520 led up tree.	g date of any propose sured and true vertica BIA. Required subseq completion in a new in ing reclamantion, hav olug at 4800'. I '. Milled on co with underrean onset packer and 00'. TIH with 5	ed work and approxi l depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk b I POOH. 5-1/2 ASI pacl CCEPTED	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. pasket. Tagged up 2- ker and 1.87" on/off	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details includin If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. To top of plug.</li> <li>10/17/02 TIH with mill and coiled tubing. Tagged plug a 10/18-20/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order D Pecos Slope Abo Oil - 0% Gas - 83.33% Wildcat Wolfcamp Oil - 0% Gas - 16.67%</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur ed out to 520 led up tree.	g date of any propose sured and true vertica BIA. Required subseq completion in a new in ing reclamantion, hav olug at 4800'. I '. Milled on co with underrean onset packer and 00'. TIH with 5	ed work and approxi l depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug pomposite plug ner and junk to I POOH. 5-1/2 ASI pacl CCEPTED FEB	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. Dasket. Tagged up 2- ker and 1.87" on/off FOR RECORD 2 0 2003	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order E Pecos Slope Abo Oil - 0% Gas - 83.33%</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur ed out to 520 led up tree.	g date of any propose sured and true vertica BIA. Required subseq completion in a new in ing reclamantion, hav olug at 4800'. I '. Milled on co with underrean onset packer and 00'. TIH with 5	ed work and approxi I depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk te I POOH. 5-1/2 ASI pacl CCEPTED FEB ARMAND	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. Dasket. Tagged up 2- ker and 1.87" on/off FOR RECORD 2 0 2003	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details includin If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. To top of plug.</li> <li>10/17/02 TIH with mill and coiled tubing. Tagged plug a 10/18-20/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order D Pecos Slope Abo Oil - 0% Gas - 83.33% Wildcat Wolfcamp Oil - 0% Gas - 16.67%</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 1 BK in hole up BOP. Ur ed out to 520 led up tree. DHC-3002	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. 1 '. Milled on co with underrean oset packer and 00'. TIH with 5	ed work and approxi l depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk be I POOH. 5-1/2 ASI pacl CCEPTED FEB ARMAND PETROLEU	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. Dasket. Tagged up 2- ker and 1.87" on/off FOR RECORD 2 0 2003	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order E Pecos Slope Abo Oil - 0% Gas - 83.33%</li> <li>Wildcat Wolfcamp Oil - 0% Gas - 16.67%</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or rec quirements, includi Tagged frac p again at 4800 l BK in hole up BOP. Ur ed out to 520 led up tree. DHC-3002	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. 1 '. Milled on co with underrean oset packer and 00'. TIH with 5 A Compliance S	ed work and approxi l depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk be I POOH. 5-1/2 ASI pacl CCEPTED FEB ARMAND PETROLEU	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. Dasket. Tagged up 2- ker and 1.87" on/off FOR RECORD 2 0 2003	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including if the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all readetermined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Tagged plug a top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order Decos Slope Abo Oil - 0% Gas - 83.33%</li> <li>Wildcat Wolfcamp Oil - 0% Gas - 16.67%</li> <li>14. I hereby certify that the foregoing is true and correct.</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 I BK in hole up BOP. Ur ed out to 520 led up tree. DHC-3002	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. 1 '. Milled on co with underrean oset packer and 00'. TIH with 5 <u>Compliance S</u> 0, 2003	ed work and approxi I depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk te I POOH. 5-1/2 ASI pacl CCEPTED FEB ARMAND PETROLEU upervisor	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. Dasket. Tagged up 2- ker and 1.87" on/off FOR RECORD 2 0 2003	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including If the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order Decos Slope Abo Oil - 0% Gas - 83.33%</li> <li>Wildcat Wolfcamp Oil - 0% Gas - 16.67%</li> <li>14. I hereby certify that the foregoing is true and correct.</li> </ul>	g estimated starting locations and meas le with the BLM/ E completion or reco quirements, includi Tagged frac p again at 4800 1 BK in hole up BOP. Ur ed out to 520 led up tree. DHC-3002	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. 1 '. Milled on co with underrean oset packer and 00'. TIH with 5 <u>Compliance S</u> 0, 2003	ed work and approxi I depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk te I POOH. 5-1/2 ASI pacl CCEPTED FEB ARMAND PETROLEU upervisor	t markers and sands. e filed within 30 days >4 shall be filed once and the operator has g 8 hours. Spotted and for 5 hours. basket. Tagged up 2- ker and 1.87" on/off FOR RECORD 2 0 2003	·1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including if the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all readetermined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Tagged plug a top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order Decos Slope Abo Oil - 0% Gas - 83.33%</li> <li>Wildcat Wolfcamp Oil - 0% Gas - 16.67%</li> <li>14. I hereby certify that the foregoing is true and correct. Name (<i>Printed' Typed</i>)</li> <li>Tina L. Huerta</li> <li>Signature</li> <li>Signature</li> <li>Approved by</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 I BK in hole up BOP. Ur ed out to 520 led up tree. DHC-3002	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. 1 '. Milled on co with underrean oset packer and 00'. TIH with 5 <u>Compliance S</u> 0, 2003	ed work and approxi I depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk te I POOH. 5-1/2 ASI pacl CCEPTED FEB ARMAND PETROLEU upervisor	t markers and sands. e filed within 30 days )-4 shall be filed once and the operator has g 8 hours. Spotted ad g for 5 hours. Dasket. Tagged up 2- ker and 1.87" on/off FOR RECORD 2 0 2003	-1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details includin If the proposal is to deepen directionally or recomplete horizontally, give subsurface t Attach the Bond under which the work will performed or provide the Bond No. on fi following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all red determined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Tagged plug a top of plug.</li> <li>10/17/02 TIH with mill and coiled tubing. Tagged plug a 10/18-20/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order E Pecos Slope Abo Oil - 0% Gas - 83.33%</li> <li>Wildcat Wolfcamp Oil - 0% Gas - 16.67%</li> <li>14. I hereby certify that the foregoing is true and correct. Name (<i>Printed/ Typed</i>)</li> <li>Tina L. Huerta</li> <li>Signature</li> <li>Signature</li> <li>Signature</li> <li>Signature</li> <li>Signature</li> <li>Sconditions of approval, if any are attached. Approval of this notice does not warrant or sertify that the applicant holds legal or equitable title to those rights in the subject lease</li> </ul>	g estimated starting locations and meas le with the BLM/ E completion or reco quirements, includi Tagged frac p again at 4800 1 BK in hole up BOP. Ur ed out to 520 led up tree. DHC-3002	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. 1 '. Milled on co with underrean oset packer and 00'. TIH with 5 <u>Compliance S</u> 0, 2003	ed work and approxi I depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk te I POOH. 5-1/2 ASI pacl CCEPTED FEB ARMAND PETROLEU upervisor	t markers and sands. e filed within 30 days >4 shall be filed once and the operator has g 8 hours. Spotted and for 5 hours. basket. Tagged up 2- ker and 1.87" on/off FOR RECORD 2 0 2003	-1/2'
<ul> <li>13. Describe Proposed or Completed Operation (clearly state all pertinent details including if the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will performed or provide the Bond No. on fil following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notice shall be filed only after all readetermined that the site is ready for final inspection.)</li> <li>10/16/02 RIH with 1.865" mill on 1-1/4" coiled tubing. Tagged plug a top of plug.</li> <li>10/17/02 TIH with 1.865" underreamer with JB. Tripped higher. Worked underreamer down 2-1/2'.</li> <li>10/21/02 Loaded tubing and nippled down tree. Nippled 10/22/02 Drilled out composite frac plug at 4800'. Clean Set packer at 3676'. Nippled down BOP. Nipp</li> <li>Well is now commingled, Administrative order Decos Slope Abo Oil - 0% Gas - 83.33%</li> <li>Wildcat Wolfcamp Oil - 0% Gas - 16.67%</li> <li>14. I hereby certify that the foregoing is true and correct. Name (<i>Printed' Typed</i>)</li> <li>Tina L. Huerta</li> <li>Signature</li> <li>Signature</li> <li>Approved by</li> </ul>	g estimated starting locations and meas le with the BLM/ B completion or reco quirements, includi Tagged frac p again at 4800 1 BK in hole up BOP. Ur ed out to 520 led up tree. DHC-3002	g date of any propose sured and true vertica BIA. Required subseq ompletion in a new in ing reclamantion, hav olug at 4800'. 1 '. Milled on co with underrean oset packer and 00'. TIH with 5 Compliance S 0, 2003	ed work and approxi l depths or pertinent uent reports shall be terval, a Form 3160 e been completed, a Milled on plug omposite plug ner and junk be I POOH. 5-1/2 ASI pack CCEPTED FEB ARMAND PETROLEU upervisor	t markers and sands. e filed within 30 days >4 shall be filed once and the operator has g 8 hours. Spotted and for 5 hours. basket. Tagged up 2- ker and 1.87" on/off FOR RECORD 2 0 2003 DA. LOPEZ IM ENGINEER	·1/2'