

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Alamogordo, NM 87410

CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 01693
30-015-10093

Indicate Type of Lease

STATE ☒

FEE ☐

State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Lease Name or Unit Agreement Name
Emire Abo Unit "G"

Well No.
32

Pool name or Wildcat
Abo

Type of Well:
OIL
WELL ☒

GAS
WELL ☐

OTHER

Name of Operator
B-P America Production Co.

Address of Operator
PO Box 1089, Eunice, New Mexico 88231

Well Location

Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line

Section 33 Township 17-S Range 28-E NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)
10' GL

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD @ 6366' PBTD 6365' CIBP @ 5774' 4 1/2" 11.60# casing Perfs 5834'-5942'

3-11-03 Tagged CIBP @ 5774'. Circ. well with MLF.
Spot 25 sks of cement @ 5774'-5396'
Pressure test casing to 300 PSI
PUH to 3514' Spot 25 sks of cement 3514'-3135'

3-12-03 PUH to 1055' Spot 25 sks of cement 1055'-677'. Tagged @ 695'
Perf @ 450' Squeezed 35 sks of cement under a packer. Displaced cement to 350'
Perf @ 60' Circulated with 10 sks of cement

Cut off wellhead and anchors 3'BGL Cap well. Install dry hole marker. Clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Jim Lutz*

TITLE

DATE 3/25/2003

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 28 2003



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

HOBBS OFFICE
APR - 7 2003
DATE REC'D.

Lori Wrotenbery

Director

Oil Conservation Division

3 April 2003

BP America Production

P.O. Box 1089

Eunice, New Mexico 88231



Form C-103 Report of Plugging for your Empire Abo Unit "G" # 32 I-33-17-28-APR 30-015-01693
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- NA ☐ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

M. Kent Whitmore
Name

BP Artesia L&L Team Leader
Title

Van Barton

Van Barton
Field Rep. II

OK to release p.