

Submit 3 Copies  
to Appropriate  
District Office

DISTRICT I  
P.O. Box 1980 Hobbs NM 88240-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
30-015-22416

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
B-2071

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
BP America Production Company

8. Well No.  
332

3. Address of Operator  
P.O. Box 1089 Eunice, NM 88231

9. Pool name or Wildcat  
Empire Abo

4. Well Location  
Unit Letter L : 1575 Feet From The S Line and 660 Feet From The W Line

Section 34 Township 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3658.4' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6250' CIBP 5960' PERFS: 6032-6140

03.25.03: Tagged CIBP @ 5960'. Circ well w/MLF.  
Spot 50' cmt @ 5960-5910'.  
PUH and spot 35 sxs cmt @ 3450-3350'. Tag cmt @ 3109'.  
PUH and spot 35 sxs cmt @ 800-700'. Tag cmt @ 645'.  
PUH and spot 35 sxs cmt @ 550-450'. Tag cmt @ 445'.  
PUH and spot 10 sxs cmt @ 60' to surf.

Cut off wellhead and anchors. Cap well. Install dry hole marker. Clean location.  
Well P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Sr. Administrative Assistant

DATE 04.01.03

TYPE OR PRINT NAME Kellie D. Murrish

TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 28 2003



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**  
Cabinet Secretary


**Lori Wrotenbery**

Director

**Oil Conservation Division**

3 April 2003

BP America Production  
P.O. Box 1089  
Eunice, New Mexico 88231



**HOBBS OFFICE**  
**APR - 7 2003**  
**DATE REC'D**

Form C-103 Report of Plugging for your Empire Abo Unit "G" # 332 L-34-17-28 API 30-015-22416  
Cannot be approved until an NMOCDD representative has made an inspection of the location and found it to  
be cleared to comply with OCD rules and regulations. Please check each item in the space provided to  
indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in  
concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name,  
well number and location including quarter/quarter section or unit letter, section, township, range and API  
well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been  
cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- NA* ☐ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been  
leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for  
plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and  
returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and  
approval.

*M. Kent Whitman*  
Name

*BP Artesia EAU Team Leader*  
Title

*[Signature]*

Van Barton  
Field Rep. II

*OK - to release*