Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised May 08, 2003		
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, winerars and readural resources			WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-015-32818		
District III	1220 South St. Francis Dr.			5. Indicate Type of Lease STATE FEE X		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & G		
1220 S. St. Francis Dr., Santa Fe, NM				0. 5	Deabe 110.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name o	г Unit Agreement N	ame
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				EDSEL'S WAND WAVER FEE		
1. Type of Well:				8. Well Number		
Oil Well Gas Well X Other RECEIVED				1		
2. Name of Operator	TON	NOV	1 E 2004	9. OGRID Numb		
MARBOB ENERGY CORPORATION NOV 1 5 20 3. Address of Operator			- · · ·	14049 10. Pool name or Wildcat		
PO BOX 227, ARTESIA, NM 88211-0227			ARTESIA		VER; MORROW	
4. Well Location					•	
Unit Letter 5 : 1650 feet from the NORTH line and 660 feet from the WEST line						
Unit Letter5_:_	1650 feet from the	NORTH	line and	660 feet fro	m the WEST	_line
Section 6	Township 2	24S Ra	inge 28E	NMPM	County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
3096 GL						
	ppropriate Box to In	dicate N				
NOTICE OF IN- PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON		SUB REMEDIAL WOR	SEQUENT RE	:PORT OF: ALTERING CASIN	ıc 🗆
PERFORM REMEDIAL WORK	PLUG AND ABANDON	Ш	REWEDIAL WOR	. П	ALTERING CASIN	10 FJ
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS.□	PLUG AND	
PULL OR ALTER CASING ☐	PULL OR ALTER CASING MULTIPLE CASING TEST A				ABANDONMENT	
	COMPLETION	_	CEMENT JOB	ND 🗌		
OTHER:			OTHER:	RECOMPLETE		X
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
or recompletion.						
RECOMPLETED IN THE MORROW ZONE AS FOLLOWS:						
$10/6/04$ - SET $4\frac{1}{2}$ " 10K COMPOSITE PLUG @ 12500'. PERF @ 12399'-12438'						
(72 SHOTS).						
10/7/04 - ACIDIZE W/ 1250 GAL CLAY SAFE H ACID. 10/11/04 - PERF @ 12244' - 12256' (66 SHOTS).						
10/11/04 - PERF @ 12244' - 12256' (66 SHO1S). 10/12/04 - ACIDIZE W/ 750 GAL CLAY SAFE H ACID.						
10/13/04 - SET 4½" 10K COMPOSITE PLUG @ 12300'.						
10/14/04 - FRAC THE MORROW @ 12244' - 12256' W/ 38750 GAL FLUID &						
25K# PROPPANT. AIP 6550#. AIR 25 BPM. ISIP 5400#.						
•						
^						
I hereby certify that the information.	above is true and comple	te to the b	est of my knowledg	e and belief.		
SIGNATURE	<u>ann</u>	TITLE	PRODUCTION A	NALYST	_DATE_11/9/0	4
Type or print name DIANA	A J. CANNON			Telep	hone No. (505)	748-3303
(This space for State use)					Aton	1 9 2004
A DDDD OVED DV		fiftrde≠ ro				T N TÔÑÀ
APPPROVED BY Conditions of approval, if any:	r records of	ALTATE			DATE	