For State Use Only
APPROVED BY

Conditions of Approval, if any:

Submit 3 Copies To Appropriate District	State of New Mo	exico		Form C-103	
Office	Energy, Minerals and Natu	ral Resources		May 27, 2004	
District I 1625 N. French Dr., Hobbs, NM 87240			WELL API NO.		
District II	OIL CONSERVATION	OIL CONSERVATION DIVISION		30-015-32353	
1301 W. Grand Ave., Artesia, NM 88210 District III		1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE 🗷	FEE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Leas	se No.	
SUNDRY NOTICE	ES AND DEDODES ON WE	110	7 7 7 7	A	
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ES AND REPORTS ON WE SALS TO DRILL OR TO DEEPEN ATION FOR PERMIT" (FORM C-10	OR PLUG BACK TO A	7. Lease Name or Unit	•	
1. Type of Well: Oil Well Gas Well X	Other	RECEIVED	8. Well Number		
2. Name of Operator		OCT 1 2 2004	9. OGRID Number		
EOG Resources Inc.		ODD ADTEQIA			
3. Address of Operator		A SOLVE THE COMPA	10. Pool name or Wildo	cat	
P.O. Box 2267 Midland, Tex	as 79702		Angel Ranch; Strawn		
4. Well Location					
Unit Letter N:	997 feet from the So	uth line and	1445 feet from the	West line	
Section 23	Township 198		· · · · · · · · · · · · · · · · · · ·	ounty Eddy	
	11. Elevation (Show whether	DR, RKB, RT, GR, et 3480	c.)		
Pit or Below-grade Tank Application					
Pit type Depth to Groundwater .		h water well Dis	stance from nearest surface wa	iter	
Pit Liner Thickness: mil			on Material		
		·			
12. Check A	ppropriate Box to Indicate	el Nature of Notice,	Report, or Other Da	ta	
NOTICE OF INTE	ENTION TO:	SUB	SEQUENT REPOR	RT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WORK		TERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	ING OPNS. 🔲 PL	UG AND X	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND		BANDONMENT	
	COMPLETION	CEMENT JOB			
OTHER:		OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
9/13/04 Spot 60 sx cemen	nt from 2850' to 2650.				
9/14/04 RIH and tag TOC					
Spot 60 sx cemen	nt from 2400' to 2200'.				
Spot 60 sx cemen	nt from 1400' to 1200'.				
Circulate 130 s	cement from 500' to suri	ace.			
Well P&A 9/14/04	! .				
I hereby certify that the information al grade tank has been/will be constructed or c	oove is true and complete to the losed according to NMOCD guidelin	best of my knowledges, a general permit	and belief. I further certify or an (attached) alternative	y that any pit or below-	
SIGNATURE Stan Way	TIT	LE Regulato	ry Analyst DAT		
Type or print name Stan Wagner	E-:	mail address:	Tolonhono	No. 422 696 2690	
-			1 elepnone	No. 432 686 3689	
For State Use Only					
APPROVED BY Conditions of Approval, if any:	TI	TLE	DATE		



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON Governor

Joanna Prukop Cabinet Secretary **Acting Director** Oil Conservation Division

RECEIVED NOV 1 7 2004 OCD:APTESIA

EOG Resources Inc. P.O. Box 2267

13 October 2004

Midland, Texas 79702

Form C-103 Report of Plugging for your Gordon 23 State Com	# 1 N-23-	19-27 API	30-015-32353
Cannot be approved until an NMOCD representative has made a	n inspection	n of the location	n and found it to
be cleared to comply with OCD rules and regulations. Please ch	eck each ite	em in the space	provided to
indicate that the work has been accomplished and the location is	ready for fi	nal inspection.	

indicate that the work has been accompnished and the location is ready for final hispection.
1. All pits have been closed as per Rule 50.
2. Rat hole and cellar have been filled and leveled.
3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
1 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment. With the life epition of EOG Radio hansmitten of antena which needs to 5. The dead men and tie downs have been cut and removed.
6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
All environmental concerns have been addressed as per OCD guidelines.
The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and

Field Rep. II