Office <u>District I</u>			exico		Form C	
	Energy, Minerals	s and Natu	ıral Resources		March 4	2004
1625 N. French Dr., Hobbs, NM 88240				WELL API NO	•	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			DIVISION	30-015-33726		
District III				5. Indicate Type		
1000 Rio Brazos Rd Aztec NM 87410			STATE			
District IV Santa Fe, NM 8/505			6. State Oil & C	Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM				1		
87505	TICES AND REPORTS C	NI WEIT C	,	7 Loose Nome	on I Init Assessment No	
(DO NOT USE THIS FORM FOR PROP					or Unit Agreement Na	me
DIFFERENT RESERVOIR. USE "APPL				Big Chief Fee		
PROPOSALS.)	(	•		O W-11 M		
1. Type of Well: RECEIVED			8. Well Number #7			
Oil Well Gas Well Other			#/			
2. Name of Operator			9. OGRID Num	nher		
	Nadel and Gussman Permian, LLC OCD-ARTESIA			155615		
3. Address of Operator			10. Pool name or Wildcat			
601 N. Marienfeld Suite 508 Midland, Texas 79701			Dublin Ranch; Morrow			
L.	idiki, Texas 77701			Dubini Nancii, i	VIOITOW	
4. Well Location						
Timis I assent . 10001	fact from the Caret	1:	od 1210'	at from the III	line	
Unit Letter L: 1980'_	feet from the South	une ai	nd 1310'1e	et from the west _	me	
Gardina 21 T		. 20 E	) II (II)			
	ownship 22-S Range		NMPN		y Eddy	anna a sa
· 随意的 17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	11. Elevation (Show w	hether DK	, RKB, RT, GR, etc			
						1.00
Pit or Below-grade Tank Application (F	or pit or below-grade tank clos	sures, a form	C-144 must be attach	<u>ed)</u>		1
Pit Location: ULL_Sect 21_Twp 22	-SRng 28-EPit type Res	erve _Depth	to Groundwater 100'_	Distance from near	rest fresh water well 1000'	+
Distance from nearest surface water 1	000'+ Relow-grade Tank	Location U	L Sect	Two Rng	:	
				- · · · · · · · · · · · · · · · · · · ·	<del></del>	
feet from theiine and	reet from the	me				
10 01-1	Appropriate Box to In		Tation of NT ation			
NOTICE OF I	NTÊNTION TO:   PLUG AND ABANDOI   CHANGE PLANS   MULTIPLE		REMEDIAL WOR COMMENCE DR	SEQUENT RI	EPORT OF: ALTERING CASING	<b>=</b>
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	NTÊNTION TO:   PLUG AND ABANDOI   CHANGE PLANS		SUE REMEDIAL WOR COMMENCE DR	SEQUENT RI	EPORT OF: ALTERING CASING PLUG AND	
NOTICE OF II PERFORM REMEDIAL WORK [ TEMPORARILY ABANDON [ PULL OR ALTER CASING [ OTHER:	NTENTION TO:   PLUG AND ABANDOI   CHANGE PLANS   MULTIPLE   COMPLETION		REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Amend	SSEQUENT RI RK   CILLING OPNS.  ND   COMPARED	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT	
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comof starting any proposed wor recompletion.	NTENTION TO:   PLUG AND ABANDO!   CHANGE PLANS   MULTIPLE COMPLETION   pleted operations. (Clear york). SEE RULE 1103.   and run 330' 13 3/8" 48#15ppsD29 + 0.2%D64 LEA	N   D  State all  For Multip  H-40 ST&  AD 200sx (	C casing. RU Schl	ESEQUENT RI  ELLING OPNS.  END  Ed Report  Ed give pertinent da  ttach wellbore diag  umberger and circus  ED29 TAIL. (Circus	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  The serior of proposed computate. Cement w/ 160 solute 113 sx to surface)	ed date
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or common of starting any proposed or common recompletion.  12/01/04 RU casing crew of the common of starting and the common of starting any proposed or common recompletion.  12/01/04 RU casing crew of the common of starting any proposed or common of starting any proposed or common recompletion.  12/01/04 RU casing crew of the common of th	NTENTION TO:    PLUG AND ABANDOI    CHANGE PLANS    MULTIPLE COMPLETION    Pleted operations. (Clearly ork). SEE RULE 1103.    And run 330' 13 3/8" 48#15ppsD29 + 0.2%D64 LEArly orductor pipe and 13 3/8"	ly state all For Multip H-40 ST&AD 200sx ( and weld o	C casing. RU Schlic +2%S1 + 0.25pps on well head. (Test	SEQUENT RICK   CILLING OPNS.  CONTROL	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  Ates, including estimate gram of proposed comp alate. Cement w/ 160 s alate 113 sx to surface) ok.)	ed date
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or com of starting any proposed w or recompletion.  12/01/04 RU casing crew of the completion of the	NTENTION TO:    PLUG AND ABANDOI    CHANGE PLANS    MULTIPLE COMPLETION    Pleted operations. (Clearly ork). SEE RULE 1103.    And run 330' 13 3/8" 48#15ppsD29 + 0.2%D64 LEArly orductor pipe and 13 3/8"	ly state all For Multip H-40 ST&AD 200sx ( and weld o	C casing. RU Schlic +2%S1 + 0.25pps on well head. (Test	SEQUENT RICK   CILLING OPNS.  CONTROL	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  Ates, including estimate gram of proposed comp alate. Cement w/ 160 s alate 113 sx to surface) ok.)	ed date
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or com     of starting any proposed v     or recompletion.  12/01/04 RU casing crew v  35/65 poz/C 6%D20 + 3%S1 + 0.2 down @ 3:13pm. WOC, cut off co	NTENTION TO:    PLUG AND ABANDOI    CHANGE PLANS    MULTIPLE COMPLETION    Pleted operations. (Clearly ork). SEE RULE 1103.    And run 330' 13 3/8" 48#15    SppsD29 + 0.2%D64 LEA onductor pipe and 13 3/8"    And run above is true and complete closed according to NMOCI	ly state all For Multip H-40 ST&AD 200sx ( and weld of	REMEDIAL WORD  COMMENCE DR  CASING TEST A CEMENT JOB  OTHER: Amend pertinent details, ar ble Completions: A  C casing. RU Schl C+2%S1 + 0.25ppc on well head. (Test	SEQUENT RI RK   CILLING OPNS.  CILLI	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  Attes, including estimate gram of proposed complate. Cement w/ 160 shale 113 sx to surface) ok.)  Ther certify that any pit or mative OCD-approved plane	ed date
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or common of starting any proposed or common recompletion.  12/01/04 RU casing crew of the common of starting and the common of starting any proposed or common recompletion.  12/01/04 RU casing crew of the common of starting any proposed or common of starting any proposed or common recompletion.  12/01/04 RU casing crew of the common of th	NTENTION TO:    PLUG AND ABANDOI    CHANGE PLANS    MULTIPLE COMPLETION    Pleted operations. (Clearly ork). SEE RULE 1103.    And run 330' 13 3/8" 48#15    SppsD29 + 0.2%D64 LEA onductor pipe and 13 3/8"    And run above is true and complete closed according to NMOCI	ly state all For Multip H-40 ST&AD 200sx ( and weld of	C casing. RU Schlic +2%S1 + 0.25pps on well head. (Test	SEQUENT RI RK   CILLING OPNS.  CILLI	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  Attes, including estimate gram of proposed complate. Cement w/ 160 shale 113 sx to surface) ok.)  Ther certify that any pit or mative OCD-approved plane	ed date
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comon of starting any proposed wor recompletion.  12/01/04  RU casing crew: 35/65 poz/C 6%D20 + 3%S1 + 0.2 down @ 3:13pm. WOC, cut off control of the	NTENTION TO:    PLUG AND ABANDOI    CHANGE PLANS    MULTIPLE COMPLETION    Pleted operations. (Clearly ork). SEE RULE 1103.    And run 330' 13 3/8" 48#15    SppsD29 + 0.2%D64 LEA onductor pipe and 13 3/8"    And run above is true and complete closed according to NMOCI	ly state all For Multip H-40 ST& AD 200sx ( and weld co	C casing. RU Schlic +2%S1 + 0.25pps on well head. (Test	BSEQUENT RI RK	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  The states, including estimate gram of proposed complate. Cement w/ 160 solitate 113 sx to surface) The certify that any pit or mative OCD-approved plants.	ed date
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or com of starting any proposed w or recompletion.  12/01/04 RU casing crew and a starting and proposed w or recompletion.  12/01/04 RU casing crew and a starting and proposed w or recompletion.  12/01/04 RU casing crew and a starting and proposed w or recompletion.  12/01/04 RU casing crew and a starting and a starting and proposed w or recompletion.  12/01/04 RU casing crew and a starting and a startin	NTENTION TO:    PLUG AND ABANDOI   CHANGE PLANS   MULTIPLE COMPLETION    Pleted operations. (Clearly ork). SEE RULE 1103.   Part of the second	ly state all For Multip H-40 ST& AD 200sx ( and weld co	REMEDIAL WORD  COMMENCE DR  CASING TEST A CEMENT JOB  OTHER: Amend pertinent details, ar ble Completions: A  C casing. RU Schl C+2%S1 + 0.25ppc on well head. (Test	BSEQUENT RI RK	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  The states, including estimate gram of proposed complate. Cement w/ 160 solitate 113 sx to surface) The certify that any pit or mative OCD-approved plants.	ed date
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comon of starting any proposed woor recompletion.  12/01/04  RU casing crew: 35/65 poz/C 6%D20 + 3%S1 + 0.2 down @ 3:13pm. WOC, cut off continuous conti	NTENTION TO:    PLUG AND ABANDOI   CHANGE PLANS   MULTIPLE COMPLETION    Pleted operations. (Clearly ork). SEE RULE 1103.   Part of the second	ly state all For Multip H-40 ST& AD 200sx ( and weld co	C casing. RU Schlic +2%S1 + 0.25pps on well head. (Test	BSEQUENT RI RK	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  The states, including estimate gram of proposed complate. Cement w/ 160 solitate 113 sx to surface) The certify that any pit or mative OCD-approved plants.	ed date
NOTICE OF II PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or com     of starting any proposed v     or recompletion.  12/01/04 RU casing crew: 35/65 poz/C 6%D20 + 3%S1 + 0.2 down @ 3:13pm. WOC, cut off co	NTENTION TO:    PLUG AND ABANDOI   CHANGE PLANS   MULTIPLE COMPLETION    Pleted operations. (Clearly ork). SEE RULE 1103.   Part of the second	ly state all For Multip H-40 ST& AD 200sx ( and weld co	C casing. RU Schlic +2%S1 + 0.25pps on well head. (Test	BSEQUENT RI RK	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  The states, including estimate gram of proposed complate. Cement w/ 160 solitate 113 sx to surface) The certify that any pit or mative OCD-approved plants.	ed date