

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised May 08, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>30.015.22895</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>647-371</b>
7. Lease Name or Unit Agreement Name: <b>Empire Abo Unit 'F'</b>
8. Well No. <b>343</b>
9. OGRID Number <b>000778</b>
10. Pool name or Wildcat <b>Empire Abo</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other

RECEIVED

2. Name of Operator  
**BP America Production Company**

DEC 16 2004

3. Address of Operator  
**P.O. Box 1089 Eunice NM 88231**

4. Well Location

Unit Letter **F** : **2300** feet from the **N** line and **1675** feet from the **W** line

Section **34** Township **17S** Range **28E** NMPM County **EDDY**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD: 6382' PBD: 6005' (CIBP W/CMT) PERFS: 5776-5908'  
10.21.04: MURUPU. NDWH. NUBOP. PREP TO PULL TBG.  
10.22.04: SET CIBP @ 6005' W/W. DUMP 35' CMT ON TOP OF CIBP. TTH W/TBG.  
LOAD & TEST CIBP TO 500# PSI FOR 30 MINS. HELD OK.  
10.26.04: SWAB BACK FLUID F/CSG. PREP TO PULL TBG.  
10.27.04: TOH W/TG. ROWL TO RUN TDT LOGS. LOG WELL. SELECT PERFS  
10.28.04: RU & PERF WELL AS FOLLOWS W/2 JSPF: 5776, 5782, 5786, 5800, 5804, 5819, 5830-35'.  
5844-58', 5854-58', 5866-68', 5883-85', 5894-98', 5906-08'. 65 HOLES TOTAL.  
10.29.04: TTH W/PKR TESTING TBG IN HOLE. SET PKR @ 5677'. PREP TO ACIDIZE.  
11.01.04: RU & ACIDIZE NEW PERFS W/2500 GALS 15% Hcl W/ADDITIVE.  
11.04.04: SWAB BACK ACID.  
11.08.04: RLS PKR. TTH TO KNOCK BALLS OFF PERFS. TOH W/PKR. TTH W/PROD TBG. NUBOP. NDWH.  
11.10.04: 2-3/8" TBG SET @ 5930'. SN @ 5931'. WELL DID NOT FLOW. SI WAITING ENGINEERING EVALUATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Staff Support DATE 12.15.04

Type or print name Kellie D. Murrish Telephone No. 505.394.1649

(This space for State use)

APPROVED BY FOR RECORDS ONLY TITLE DATE  
Conditions of approval, if any:

DEC 17 2004