	State of New Mexico		Form C-103
Office <u>District I</u>	Energy, Minerals and Natural Resources		WELL API NO.
625 N. French Dr., Hobbs, NM 88240 District II			30-015-01480
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE TEE
District IV Santa Fe, NM 8/505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-2178
	S AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL			Delia de la marco
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Socii	Red Lake Sand Unit
1. Type of Well: RECEIVED		CEIVED	8. Well Number
Oil Well Gas Well O	ther Injection		17
2. Name of Operator		0 9 2004	9. OGRID Number
Mack Energy Corporation	on OCD.	ARTESIA	10 Post sees wilder
3. Address of Operator		-	10. Pool name or Wildcat
P.O. Box 960, Artesia,	NM 88211-0960		Red Lake Shore; Grayburg
Unit Letter M : 3	feet from the South	line and	990 feet from the West line
			P. I.
Section 20	Township 17S Rang	ge 28E	NMPM County Eddy
	1. Elevation (Show whether DR, R 3562 GR	KB, KI, GR, etc.)	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)			
Pit Location: ULSectTwpRngPit typeDepth to GroundwaterDistance from nearest fresh water well			
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng;			
feet from theline and			,
	propriate Box to Indicate Nat		
NOTICE OF INTE			SEQUENT REPORT OF:
FERFORM REMEDIAL WORK	TOG AND ABANDON []	REMEDIAL WORK	C ☐ ALTERING CASING ☐
TEMPORARILY ABANDON 🔲 (	CHANGE PLANS	COMMENCE DRIL	LING OPNS.□ PLUG AND 🖄
DULL OD ALTED CACING	41171015	04000 TEOT 44	ABANDONMENT
	_ ,	CASING TEST AN	ABANDONMENT
	COMPLETION	CEMENT JOB	ABANDONMENT  ID
	COMPLETION		ABANDONMENT
OTHER:  13. Describe proposed or complete	COMPLETION (Clearly state all per	CEMENT JOB  OTHER:  rtinent details, and	ABANDONMENT  ID    give pertinent dates, including estimated date
OTHER:  13. Describe proposed or complete of starting any proposed work)	COMPLETION (Clearly state all per	CEMENT JOB  OTHER:  rtinent details, and	ABANDONMENT  ID
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple	CEMENT JOB OTHER: rtinent details, and Completions: Att	ABANDONMENT  ID  Give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @	ed operations. (Clearly state all per b. SEE RULE 1103. For Multiple	CEMENT JOB OTHER: rtinent details, and Completions: Att	ABANDONMENT  ID  Give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/	ed operations. (Clearly state all per b. SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud.	CEMENT JOB OTHER: rtinent details, and Completions: Att	ABANDONMENT  ID    give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes	completion  cod operations. (Clearly state all per code). SEE RULE 1103. For Multiple  1626', cap w/ 35' cmt mud.  @ 537' set pkr. @ 250	CEMENT JOB OTHER: rtinent details, and Completions: Att t. w/ bailer	ABANDONMENT  ID  Give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes	ed operations. (Clearly state all per b. SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt.	CEMENT JOB OTHER: rtinent details, and Completions: Att t. w/ bailer	ABANDONMENT  ID    give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt.	CEMENT JOB OTHER: rtinent details, and Completions: Att t. w/ bailer O' sqz. 40 s	ABANDONMENT    D
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30  I hereby certify that the information about the second starting of the se	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt. '.	CEMENT JOB  OTHER:  rtinent details, and Completions: Att  t. w/ bailer  o' sqz. 40 s	ABANDONMENT    D
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30  I hereby certify that the information about the second starting of the se	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt. '.	CEMENT JOB  OTHER:  rtinent details, and Completions: Att  t. w/ bailer  o' sqz. 40 s	ABANDONMENT    D
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30  I hereby certify that the information about the second starting of the se	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt. '.	CEMENT JOB  OTHER:  rtinent details, and Completions: Att  t. w/ bailer  o' sqz. 40 s	ABANDONMENT  ID     give pertinent dates, including estimated date ach wellbore diagram of proposed completion    ack cmt. tag plug @ 269'.   ack cmt. tag plug @ 269'.   and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan   .
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30  I hereby certify that the information aborded tank has been/will be constructed or close SIGNATURE	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt.  "  Dive is true and complete to the best sed according to NMOCD guidelines [],	CEMENT JOB OTHER: rtinent details, and Completions: Att t. w/ bailer O' sqz. 40 s co t of my knowledge a general permit	ABANDONMENT    D
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30  I hereby certify that the information aborded tank has been/will be constructed or close	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt.  "  Ove is true and complete to the best sed according to NMOCD guidelines [],	CEMENT JOB OTHER: rtinent details, and Completions: Att t. w/ bailer O' sqz. 40 s co t of my knowledge a general permit	ABANDONMENT  ID     give pertinent dates, including estimated date ach wellbore diagram of proposed completion    ack cmt. tag plug @ 269'.   ack cmt. tag plug @ 269'.   and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan   .
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30  I hereby certify that the information aborded tank has been/will be constructed or close SIGNATURE	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt.  "  Dive is true and complete to the best sed according to NMOCD guidelines [],	CEMENT JOB OTHER: rtinent details, and Completions: Att t. w/ bailer O' sqz. 40 s co t of my knowledge a general permit	ABANDONMENT    D
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30  I hereby certify that the information aborgande tank has been/will be constructed or close SIGNATURE  Type or print name  (This space for State use)	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt.  "  Dive is true and complete to the best sed according to NMOCD guidelines [],	CEMENT JOB OTHER: rtinent details, and Completions: Att t. w/ bailer O' sqz. 40 s co t of my knowledge a general permit	ABANDONMENT    D
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30  I hereby certify that the information aborgande tank has been/will be constructed or close SIGNATURE  Type or print name  (This space for State use)  APPPROVED BY	ed operations. (Clearly state all per ). SEE RULE 1103. For Multiple 1626', cap w/ 35' cmt mud. @ 537' set pkr. @ 250 @ 60' sqz. 35 sx cmt.  "  Dive is true and complete to the best sed according to NMOCD guidelines [],	CEMENT JOB OTHER: rtinent details, and Completions: Att t. w/ bailer O' sqz. 40 s co t of my knowledge a general permit	ABANDONMENT    D
OTHER:  13. Describe proposed or complete of starting any proposed work) or recompletion.  8-27-04 Set 7" CIBP @ 8-30-04 Circ. hole w/ 8-30-04 Perf. 4 holes 8-30-04 Perf. 4 holes 8-31-04 Tag plug @ 30  I hereby certify that the information aborgrade tank has been/will be constructed or close SIGNATURE  Type or print name  (This space for State use)	ed operations. (Clearly state all per complete of the complete	CEMENT JOB OTHER: rtinent details, and Completions: Att t. w/ bailer O' sqz. 40 s co t of my knowledge a general permit	ABANDONMENT    D

Page 2 Mack Energy Red Lake Sand Unit #17

8--31--04 Pump 10 sx cmt. from 30' to surface tag @ 3'. 8--31--04 RDMO. Install dry hole marker & clean location.



## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON Governor

Joanna Prukop **Cabinet Secretary Acting Director** Oil Conservation Division

14 September 2004

Mack Energy Corp. P. O. Box 960

Artesia, New Mexico 88221-0960

Form C-103 Report of Plugging for your Red Lake Sand Unit # 17 M-20-17-28 API 30-015-01480 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection. RECEIVED

1. All pits have been filled and leveled.

DEC 2 8 2004

2. Rat hole and cellar have been filled and leveled.

**MIRRALASIO** 

- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 1 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 🛛 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.

☑7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Field Rep. II