Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

N.M. Oil Cons. DIV-Dist. 2

FORM APROVED OMB NO. 1004-0135

1301 W. Grand Avenuexpires: NOVEMBER 30, 2000

Artesia, NM 882 1 6 ase Serial No. Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals NMNM100561 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE 7. Unit or CA Agreement Name and No. RECEIVE NMNM106850 1a. Type of Well Oil Well Gas Well 8 Well Name and No. STRAWBERRY 7 FED COM 1 2. Name of Operator **DEVON ENERGY PRODUCTION COMPANY, LP** 9. API Well No. 3. Address and Telephone No. 30-015-31876 405-552-4615 10. Field and Pool, or Exploratory 20 North Broadway, Ste 1500, Oklahoma City, OK 73102 Location of Well (Report location clearly and in accordance with Federal requirements)* N HACKBERRY 660 FNL 1750 FWL Unit Letter "C", Sec 7-19S-31E 12. County or Parish 13. State **EDDY COUNTY, NM** NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Production (Start/Resume) Water Shut-Off __ Acidize Deepen ✓ Notice of Intent Reclamation Fracture Treat Well Integrity Alter Casing Subsequent Report Casing Repair Recomplete Other **New Construction** Temporarily Abandon Plug and Abandon Change Plans Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) Notice of Intent: Recomplete from Wolfcamp to Bone Spring 1. Abandon Wolfcamp (9961'-9990') by setting CIBP at 9900'. Dump 35' cement on top. 2. Perforate the Bone Spring at 9590' - 9620'. Acidize with 2500 gallons 7.5% acid. Frac w/ 65K# 16/30. 3. Hang well on and test to production. 4. Add additional Bone Spring pay at 9352' - 9362'. Hang well on pump and test. 5. Add additional Bone spring pay at 8716' - 8744'. Hang well on pump and test. Acidize and frac if necessary. 6. Turn well over to production. APPROVED ALEXIS C. SWOBODA PETROLEUM ENGINEER 14. I hereby certify that the foregoing is true and correct Name Ronnie Slack 2/24/05 Title Engineering Technician (This space for Federal or State Office use) Title Date Conditions of approval, if any: Section 1001, makes it a crime to any person knowingly and willout to make any department of adency or me crimeto states any raise includes or material