Submit 3 Copies To Appropriate District State of New Mexico Form C-10	<i>J J</i>
Office Energy, Minerals and Natural Resources March 4, 20	04_
District I 1625 N. French Dr., Hobbs, NM 88240 WELL API NO.	$\neg \gamma$
30_015_33741	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION 5 Indicate Type of Lease	
District III 1220 South St. Francis Dr. STATE M FEE	ļ
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505 6 Stote Oil & Cos Leges No.	
District 1 V	- 1
1220 S. St. Francis Dr., Santa Fe, NM 87505	i
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name	•
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Kurgan State	'
DIFFERENT RESERVOIR LISE "APPLICATION FOR PERMIT" (FORM C-10)1 FOR SUCH	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C.101) FOR SUCH PROPOSALS.)	
1. Type of Well:	
Oil Well Gas Well 🛛 Other MAR 0 1 2005 #1	
	\dashv
	1
Nadel and Gussman Permian, LLC 155615	_
3. Address of Operator 10. Pool name or Wildcat	1
601 N. Marienfeld Suite 508 Midland, Texas 79701 Burton Flat (Morrow) 73280	
4. Well Location	
4. Well Excation	
Unit Letter A : 660' feet from the North line and 660' feet from the East line	
Omit Letter A: 000lest from the North line and 000lest from the Eastline	
Control of	
Section 16 Township 21-S Range 27-E NMPM County Eddy	96121295°\
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	EDE NA
3279	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: UL A_ Sect 16_ Twp 21-S_ Rng 27-E_ Pit type Reserve _Depth to Groundwater 100' +_ Distance from nearest fresh water well 1000'+_	- 1
Distance from nearest surface water 1000'+ Below-grade Tank Location UL Sect Twp Rng ;	
feet from the line and feet from the line	1
I THE	
TOTALLANDE THE STATE STA	
TOO II VIII MIE INC AIM ICCI II VIA MIE INC	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SEMEDIAL WORK ALTERING CASING [TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND [
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Amended Report	<u> </u>
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Amended Report I	date
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Amended Report COMPLETION 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complete	date
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Amended Report I	date
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Amended Report COMPLETION 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complete	date
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Amended Report 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed or recompletion.	date
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Amended Report CASING TEST AND CEMENT CEM	date
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 sc class C (full returns circ. 101 sx. Rig down and WOC 18 hrs.	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 sc class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/24/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 sc class C (full returns circ. 101 sx. Rig down and WOC 18 hrs.	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 sc class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/24/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 sc class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/24/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 st class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/23/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing 1,000 psi for 30 min.	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 st class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/23/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing 1,000 psi for 30 min. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belgrade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ or an (attached) alternative OCD-approved plan □	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 st class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/23/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing 1,000 psi for 30 min. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belgrade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ or an (attached) alternative OCD-approved plan □	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Amended Report OTHER: Amended Report OTHER: Amended Report OTHER: Attach wellbore diagram of proposed complete or recompletion. 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated or starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 12/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 st class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 12/24/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing 1,000 psi for 30 min. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any plt or below.	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ PLUG AND ABANDONMENT PULL OR ALTER CASING ☐ MULTIPLE ☐ CASING TEST AND ☐ CEMENT JOB OTHER: ☐ OTHER: Amended Report ☐ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 st class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/23/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing 1,000 psi for 30 min. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belegrade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan [SIGNATURE ☐ DATE ☐	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 st class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/23/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing 1,000 psi for 30 min. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belgrade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ or an (attached) alternative OCD-approved plan □	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT PULL OR ALTER CASING □ MULTIPLE □ CASING TEST AND □ CEMENT JOB OTHER: □ OTHER: Amended Report □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complete or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 sc class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/24/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing 1,000 psi for 30 min. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any plt or belegrade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ or an (attached) alternative OCD-approved plan ESIGNATURE □ TITLE Staff Engineer □ DATE 02/24/05 □ Type or print name Josh Fernau E-mail address: joshf@naguss.com Telephone No. 432-682-4429	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Amended Report CASING TEST AND CEMENT JOB OTHER: Amended Report CASING TEST AND CEMENT JOB 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet or recompletion. 02/23/05 Depth 442' Rig up casing crew. Run 13 3/8" 48# H-40 11 joints. Cement casing with lead 200 sx 35/65 poz and tail 200 sx class C (full returns circ. 101 sx. Rig down and WOC 18 hrs. 02/24/05 Cut off conductor and casing, weld on head, test well head to 500 psi. NU 13 5/8" BOP and test 250# - 1000#. Test casing 1,000 psi for 30 min. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belt prade tank has been/will be constructed or closed according to NMOCD guidelines a general permit or an (attached) alternative OCD-approved plan [SIGNATURE	date tion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK	date tion