TYPE OR PRINT

APPROVED BY

(This space for State Use)

CONDITIONS OF APPROVAL, IF AN

State of New Mexico Energy, Minerals and Natural Resources Department

JOSÉPH J. KELLY

Form C-103

505-623-3190

TELEPHONE NO

Revised 1-1-89 District Office **OIL CONSERVATION DIVISION** DISTRICT I 2040 South Pacheco WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-005-63505 Santa Fe, New Mexico 87505 5. Indicate Type of Lease X STATE FEE 1301 W. Grand Ave., Artesia, NM 88210 DISTRICT III 6 State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" RECEIVED (FORM C-101) FOR SUCH PROPOSALS.) Type of Wel OIL GAS MAR 0 2 2005 RANDALL FEE X OTHER WELL WELL. OCU-AMIESIA 8 Well No. Name of Operator **ELK OIL COMPANY** 9. Pool Name or Wildcat 3. Address of Operator POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310 WILDCAT 4. Well Location 1650 SOUTH 330 EAST Line Feet From The Unit Letter Feet From The 10 SOUTH **27 EAST** CHAVES Section Township NMPM County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3717' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) Intend to Plug and Abandon Well as Follows: (1) Move in and rig up, rig up steel pit. (2) Set CIBP @ 6800' - Dump 35' (3 sxs) on top. (3) Spot 25 sxs @ 4800'-4700'. (4) Pull 4000' of 5 1/2" casing. (5) Spot 45 sxs @ 4050'-3950' and tag. (6) Spot 45 sxs @ 1650'-1550' and tag. (7) Spot 35 sxs @ 350'-250'. (8) Spot 10 sxs @ 30'-Surface, Cut off, Install dry hole marker, rig down. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE 03/01/05

Field Anyporter