

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB 1122741907

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 105 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name NDDUP Unit #23	API Number 30-015-28424	Facility Type Well

Surface Owner State	Mineral Owner State	Lease No. LG-864
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter K	Section 16	Township 19S	Range 25E	Feet from the 1780'	North/South Line South	Feet from the 1980'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.65859 Longitude 104.49138

NATURE OF RELEASE

Type of Release Produced Water; Iron Sulfide	Volume of Release 5-10 B/PW; Iron Sulfide	Volume Recovered 0 B/PW; Iron Sulfide
Source of Release Tank valve open	Date and Hour of Occurrence 7/11/2011	Date and Hour of Discovery 7/11/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A	RECEIVED JUL 22 2011 NMOCD ARTESIA
Describe Cause of Problem and Remedial Action Taken.* An operator was moving a rectangle tank and did not check the back valve to ensure that it was closed. When the tank was shifted and tilted, 500 barrels of produced water ran out of the tank and onto the location.	

Describe Area Affected and Cleanup Action Taken.* An approximate area of 10' X 30' (all released water was contained on the wellpad). A crew was called out to location to excavate the impacted soils. The impacted soil will be taken to a NMOCD approved facility. Depth to Ground Water: 50-99" (approximately 95', Section 16, T19S-R25E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on the amount spilled and that impacted soils have been removed, Yates Petroleum Corporation requests closure.
--

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Cannon</i>	OIL CONSERVATION DIVISION	
Printed Name: Amber Cannon	Signed By <i>Mike Brennan</i>	
Title: Environmental Regulatory Agent Trainee	Approval Date: AUG 15 2011	Expiration Date:
E-mail Address: acannon@yatespetroleum.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: Friday, July 22, 2011 Phone: 575-748-4111		

* Attach Additional Sheets If Necessary

9/15/2011

2RP-846