

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/11/2018
NMOCD Dist 2

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1809438477

OPERATOR

Initial Report Final Report

Name of Company: Marathon Oil Permian LLC	Contact: Callie Karrigan
Address: 5555 San Felipe Street, Houston, Texas 77056	Telephone No.: 575-297-0956
Facility Name: Sterling 20 State 1H	Facility: Tank Battery

Surface: Owner: State	Mineral: Owner: State	API No. : 30-015-42731
-----------------------	-----------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
O	17	23S	27E	240'	South	1950'	East	Eddy

Latitude 32.2985. Longitude -104.2086

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release 51 bbl	Volume Recovered: 40 bbl
Source of Release: Human Error	Date and Hour of Occurrence 02/02/2018 05:40 am	Date and Hour of Discovery 02/02/2018 05:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver - NMOCD	
By Whom?: Callie Karrigan	Date and Hour: 02/02/2018 02:51 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
Not applicable.

Describe Cause of Problem and Remedial Action Taken.* A driver error during truck load/unload resulted in the release of approximately 51 barrels of crude oil in the lined containment. A vac truck was immediately called to location and recovered approximately 40 barrels of fluid. Talon mobilized personnel for an initial site assessment the same day.

Describe Area Affected and Cleanup Action Taken.*

The impacted gravel/soil on top of the liner was hand shoveled into a backhoe bucket and stockpiled on plastic. Peat moss and absorbent pads was used to recover any existing fluids from on top of the liner and around the bottom of tanks. A liner assessment was conducted and concluded that the liner maintained integrity. A total of 45 tons of impacted material was transported to Lea Land LLC. No further actions are required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		OIL CONSERVATION DIVISION	
Signature: <i>Callie Karrigan</i>	Approved by Environmental Specialist: 		
Printed Name: Callie Karrigan			
Title: HES Environmental Professional	Approval Date: 5/11/18	Expiration Date: N/A	
E-mail Address: cnkarrigan@marathonoil.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 03/20/2018 Phone: 575-297-0956	FINAL		

* Attach Additional Sheets If Necessary

2RP-4690

Before

