

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company XTO Energy	Contact Kyle Littrell
Address 3104 E Greene Street Carlsbad, N.M. 88220	Telephone No. 432-221-7331
Facility Name PLU 151	Facility Type Exploration and Production

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-31595
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 6	Township 24S	Range 30E	Feet from the 510	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.25264 Longitude -103.91865 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 7 bbls PW	Volume Recovered 0 bbls
Source of Release Corrosion to 2x1 swedge	Date and Hour of Occurrence 12-7-15 @ 3:00pm	Date and Hour of Discovery 12-7-15 @ 3:38 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Amy Ruth	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*

BOPCO EHS was notified of the release that occurred when a hole developed in a 2x1 swedge caused by corrosion. A vacuum truck was called but no fluid was able to be recovered. The majority of the fluid stayed on the well pad with the exception of 1.1 barrels ran off the north side of the pad.



Describe Area Affected and Cleanup Action Taken.*

The majority of the fluid stayed on the well pad with the exception of 1.1 barrels ran off the the north side of the pad. The failed swedge and connections were replaced with HP stainless steel.

The impacted soil was excavated, and confirmation soil samples were collected from the side walls and bottom of the excavation on February 12, 2018, June 27, 2018 and June 28, 2018. Laboratory analytical results from 18 confirmation soil samples indicate concentrations of BTEX, TPH, and chloride do not exceed NMOCD remediation action levels. Based on the results of confirmation samples, XTO requests no further action for this release and will backfill with clean caliche and re-contour.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Kyle Littrell	Approval Date: 09/11/18	Expiration Date: N/A
Title: SH&E Coordinator	Conditions of Approval:	
E-mail Address: Kyle_Littrell@xtoenergy.com	Like Approval BLM	Attached <input type="checkbox"/>
Date: 8/27/2018	Phone: 432-221-7331	

* Attach Additional Sheets If Necessary

A#pAB1534455004

I#nAB1534455140

FINAL 2RP-3439