

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: RECEIVED Oil Well ☒ Gas Well ☐ Other ☐		WELL API NO. 30-015-22649 5. Indicate Type of Lease STATE ☒ FEE ☐ 6. State Oil & Gas Lease No. V-1652 7. Lease Name or Unit Agreement Name: H&S State
2. Name of Operator Harvard Petroleum Corporation	MAR 23 2005	8. Well No. 1
3. Address of Operator PO Box 936, Roswell, NM 88201	COOPERATIVE	9. Pool name or Wildcat W. Millman, Grayburg
4. Well Location Unit Letter <u>J</u> : 1980 feet from the <u>South</u> line and 1980 feet from the <u>East</u> line Section <u>24</u> Township <u>19S</u> Range <u>27E</u> NMPM Eddy County		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3498.6 GR		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Casing Integrity Test for TA status ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Estimated start date - 3/24/05

MIRU PU and plugging equipment

TH, Spot 35 sx "C" + 2% CaCl plug from 1750 to 1650, WOC, tag plug.

mix mud (25sx gel/100 bbls brine), circ hole,

spot 35 sx "C" plug 485 to 385 across 13 3/8" shoe, WOC, tag plug.

spot 20 sx "C" plug from 60' to surface, make sure surface plug does not fall back.

clean up location.

Erect P&A marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 3/22/05

Type or print name Jeff Harvard

Telephone No. 505-623-1581

(This space for State use)

APPROVED BY [Signature] TITLE Field Engineer DATE 3/23/05

Conditions of approval, if any:

Notify OCD 24 hrs. prior to any work done

If this work requires an earthen pit, a permit must be approved prior to construction of the pit(s).



HARVARD PETROLEUM CORPORATION

TELEPHONE 505 823-1581

P.O. BOX 836

ROSWELL, NEW MEXICO 88201

GL: 3498.6

KB:

- WELL DATA -

LEASE NAME: H & S

WELL #: 41 API # 30 015 221049

LOCATION: J - 1980 OFL 1980 FEL

FIELD NAME: 24 - 195 - 27E, 8004 CON

SPUD DATE: 9/9/72

COMPLETION DATE:

PRODUCTION DATE:

SURFACE CSG: 13 3/8 45" H-40

SURFACE CEMENT: 400 SX "C" + 2% CCL
CIRC 10 SX

SURFACE CSG.

SET @: 432'

INTER

PRODUCTION CSG: 9 5/8 36" K-55

TOP OF CEMENT @: SURF (CIRC 40 SX)

PRODUCTION STRING CEMENT:

600 SX 16000 LITZ + ADDITIVES

200 SX "C" + 2% CCL

PRODUCED

25 SX PLUG
1620
1780-

TUBING:

EOT:

SN @: _____

FROM: 1814

TO: 1916

SHOTS/FOOT

28 holes

FORMATION: GRAY BUNCH

APPROX. OIL/WATER @: _____

PERFS:

PBT: 2430'

INTERMEDIATE

PRODUCTION CSG:

SET @: 2495'

RODS: 3/4" =

7/8" =

PUMP INFO:

35 SX "H" PLUG
3472 - 3340 W + OUT OF 7" STUB

25 SX "H" PLUG 6200 - 6700

PLUG 30 SX "H" 10042 TO 9850

10,005 7" 23" CSG

25 SX "H" PLUG 10,993 - 10,700

TOP 9541
LINEP 822
0835-48

TD - 11,089'

RECEIVED

MAR 23 2005

OCD-ARTESIA