Office _	State of New Mexico	Form C-103
District I Energy	, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL (CONSERVATION DIVISION	30-005-60787
	220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE X FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		L-4920
SUNDRY NOTICES AND R	EPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRIL		State JA
DIFFERENT RESERVOIR. USE "APPLICATION FOR P	ERMIT" (FORM C-101) FOR SUCH	Suito 371
PROPOSALS.)	7 ou	8. Well Number 1
1. Type of Well: Oil Well Gas Well	Other RECEIVEL	
2. Name of Operator	1,202.10	9. OGRID Number
Southwest Royalties, Inc.	MAR 3 1 2005	021355
3. Address of Operator		10. Pool name or Wildcat
6 Desta Drive, Ste 2100, Midland, Texas 7970.	ACD-VAI FAIV	Lost Lake Strawn
4. Well Location		
Unit Letter F 1980 feet from the N line and 1980 feet from the W line		
	Township 08S Range 29E	NMPM Chaves County
	on (Show whether DR, RKB, RT, GR, etc.)	
4074.4 GL		19 April 19
Pit or Below-grade Tank Application or Closure		
1	tance from nearest fresh water well Dist	ance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank; Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:		
NOTICE OF INTENTION	TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK X PLUG AND ABANDON 🗌 REMEDIAL WORK 🔲 ALTERING CASING 🗌		
TEMPORARILY ABANDON		
PULL OR ALTER CASING	COMPL CASING/CEMENT	rjob □
	reduction OTHED:	
OTHER: Remove salt pluggings & return to p		<u>U</u> _
13. Describe proposed or completed operation	ons. (Clearly state all pertinent details, and	I give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU	ons. (Clearly state all pertinent details, and	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
13. Describe proposed or completed operation	ons. (Clearly state all pertinent details, and	
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion.	ons. (Clearly state all pertinent details, and JLE 1103. For Multiple Completions: At	
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion.1) MI & RU WSU. Kill well with water if	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary.	
 13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if Release tubing anchor and pull tubing a 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary.	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if Release tubing anchor and pull tubing a TIH w/bit and 5-1/2" casing scrapper. 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indeed to the completion of the completi	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if Release tubing anchor and pull tubing a TIH w/bit and 5-1/2" casing scrapper. C Re-run production tubing and tubing and 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indeed to the completion of the completi	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if Release tubing anchor and pull tubing a TIH w/bit and 5-1/2" casing scrapper. 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indeed to the completion of the completi	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if Release tubing anchor and pull tubing a TIH w/bit and 5-1/2" casing scrapper. C Re-run production tubing and tubing and 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indeed to the completion of the completi	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if Release tubing anchor and pull tubing a TIH w/bit and 5-1/2" casing scrapper. C Re-run production tubing and tubing and 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indeed to the completion of the completi	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. C Re-run production tubing and tubing and Swab well in and return to production. 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indicate the state of th	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. C Re-run production tubing and tubing and 5) Swab well in and return to production. 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Ind tubing anchor Firculate fresh water to remove salt plugging thor.	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. C Re-run production tubing and tubing and 5) Swab well in and return to production. 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indicate the state of th	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if Release tubing anchor and pull tubing a TIH w/bit and 5-1/2" casing scrapper. CA Re-run production tubing and tubing and Swab well in and return to production. If this work is earthen pit, a 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indicate the state of the	tach wellbore diagram of proposed completion
 13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the Re-run production tubing and tubing and Swab well in and return to production. If this work is a carthen pit, a be approved. 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indicate the state of the	tach wellbore diagram of proposed completion
 Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. MI & RU WSU. Kill well with water if Release tubing anchor and pull tubing a TIH w/bit and 5-1/2" casing scrapper. CA Re-run production tubing and tubing and Swab well in and return to production. If this work is earthen pit, a 	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indicate the state of the	tach wellbore diagram of proposed completion
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the completion and tubing and tubing and service with the completion. If this work rearthen pit, a be approved construction	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indicate the state of the permit must prior to of the pit(s).	tach wellbore diagram of proposed completion
 13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the Re-run production tubing and tubing and Swab well in and return to production. If this work is a carthen pit, a be approved. 	necessary. Indicate the horizontal and the prior to prior to of the pit(s). The prior to the pit(s). The complete to the best of my knowledge.	tach wellbore diagram of proposed completion ag.
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the second work is a second with the construction. If this work is a carthen pit, a be approved construction. I hereby certify that the information above is true grade tank has been/will be constructed or closed according to the constructed or closed acco	ons. (Clearly state all pertinent details, and ILE 1103. For Multiple Completions: At necessary. Indicate the state of the pit (S). The permit must prior to of the pit (S). The permit must of the pit (S). The permit must of the pit (S).	e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the completion in the completion of the completion. If this work is approved construction. I hereby certify that the information above is true.	necessary. Indicate the horizontal and the prior to prior to of the pit(s). The prior to the pit(s). The complete to the best of my knowledge.	e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the completion and tubing and tubing and serving production tubing and tubing and serving swab well in and return to production. If this work is a carthen pit, a be approved construction. I hereby certify that the information above is true grade tank has been/will be constructed or closed according SIGNATURE	necessary. Indicate the best of my knowledger to NMOCD guidelines \(\bar{\text{J}}, \) ageneral permit \(\bar{\text{J}}, \) and complete to the best of my knowledger to NMOCD guidelines \(\bar{\text{J}}, \) a general permit \(\bar{\text{J}}, \) and complete to the dest of my knowledger to NMOCD guidelines \(\bar{\text{J}}, \) a general permit \(\bar{\text{J}}, \)	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan stant DATE 3/29/05_
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the completion and tubing and tubing and serving production tubing and tubing and serving swab well in and return to production. If this work is approved construction I hereby certify that the information above is true grade tank has been/will be constructed or closed according SIGNATURE	necessary. Indicate the best of my knowledger to NMOCD guidelines \(\bar{\text{J}}, \) ageneral permit \(\bar{\text{J}}, \) and complete to the best of my knowledger to NMOCD guidelines \(\bar{\text{J}}, \) a general permit \(\bar{\text{J}}, \) and complete to the dest of my knowledger to NMOCD guidelines \(\bar{\text{J}}, \) a general permit \(\bar{\text{J}}, \)	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan stant DATE 3/29/05_
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of 3 Re-run production tubing and tubing and 5) Swab well in and return to production. If this work is earthen pit, a be approved construction I hereby certify that the information above is true grade tank has been/will be constructed or closed according SIGNATURE Type or print name Dawn M. Howard E-mail For State Use Only	necessary. Indicate the best of my knowledger to NMOCD guidelines \(\bar{\text{J}}, \) ageneral permit \(\bar{\text{J}}, \) and complete to the best of my knowledger to NMOCD guidelines \(\bar{\text{J}}, \) a general permit \(\bar{\text{J}}, \) and complete to the dest of my knowledger to NMOCD guidelines \(\bar{\text{J}}, \) a general permit \(\bar{\text{J}}, \)	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan stant DATE 3/29/05_
13. Describe proposed or completed operation of starting any proposed work). SEE RU or recompletion. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the construction and return to production. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the construction and return to production. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the construction and return to production. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing a 3) TIH w/bit and 5-1/2" casing scrapper. Of the construction and return to production. 1) MI & RU WSU. Kill well with water if 2) Release tubing anchor and pull tubing and tubing and tubing anchor and return to production. 1) This work is a construction and return to production. 1) This work is a construction and return to production. 1) This work is a construction and return to production. 2) Swab well in and return to production. 2) This work is a construction and return to production. 2) This work is a construction and return to production. 2) This work is a construction and return to production. 2) This work is a construction and return to production.	necessary. Indicate the horizontal and tubing anchor Inculate fresh water to remove salt plugging thor. The prior to of the pit(s). TITLE Operations Assistant in the prior in the prior of t	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan stant DATE 3/29/05_