

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ALAMO PERMIAN RESOURCES, LLC	Contact	STEVEN MASTIN
Address	415 W. WALL ST. SUITE 500	Telephone No.	432 557 5847
Facility Name	BERRY A 33	Facility Type	

Surface Owner	FEDERAL	Mineral Owner	FEDERAL	API No.	30-015-25154
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	24	17S	27E	1650	S	2040	W	EDDY

Latitude 32.8168411354531

Longitude -104.234151895391

RECEIVED

APR 3 2012

NATURE OF RELEASE

NMOCD ARTESIA

Type of Release: WATER	Volume of Release: 50 BBLs	Volume Recovered: 30
Source of Release: INJECTION PUMP	Date and Hour of Occurrence: MAR 30, 2012	Date and Hour of Discovery: MAR 30, 2012
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? STEVEN MASTIN	No notification provided to NMOCD as required 19.15.29 NMAC
By Whom? RICKY RODRIGUEZ, FIELD SUPERVISOR	Date and Hour: MAR 30, 2012 9:00 A.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Cause of problem: Mechanical failure of injection pump fitting

Describe Area Affected and Cleanup Action Taken.*

There was approximately 10 bbls of injected water released inside the burned area near the injection pump and another 10 bbls on the other lined, burned area. Thirty bbls was recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Carie Stoker

Printed Name: CARIE STOKER

Title: REGULATORY/ PRODUCTION TECH

E-mail Address: cstoker@helmsol.com

Date: 03/30/2012

Phone: 432 664 7659

OIL CONSERVATION DIVISION

Signed By

M. L. Brumley

Approved by Environmental Specialist:

Approval Date: APR 11 2012

Expiration Date:

Conditions of Approval:

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPC N LATER THAN:
5 11 012

Attached ☐

2RP-1089

* Attach Additional Sheets If Necessary