## Form 3160-5 (February 2005)

OCD-ARTESIA

## UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APROVED OMB NO 1004-0135 EXPIRES. March 31, 2007

5 Lease Serial No

**BUREAU OF LAND MANAGEMENT** SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an		NMNM 36379; K 4562		
	6. It India	n, Allottee or Tribe N	vame	
SUBMIT IN TRIPLICATE	7 Unit o	r CA Agreement Nar	me and No	
a. Type of Well Gas Well Other	Unit or CA Agreement Name and No.     NM 709284			
	8 Well N	ame and No		
2. Name of Operator	Cotton Draw Unit 135H			
	9. API Well No			
3. Address and Telephone No.	30-315-38533			
20 N Broadway, Oklahoma City, Ok 73102-8260 405-235-3611 10 Field and Pool, or Exploratory		atory		
Location of Well (Report location clearly and in accordance with Federal requirements)*		Paduca; Bone Spring		
200 FSL 1600 FWL N SEC 2 T25S R31E		11 County or Parish State		
3HL 2626 FSL & 1001 FWL L SEC 35 T24S R31E PP: 85 FSL 1745 FWL	Eddy	NM		
12. CHECK PAROBRIATE BOX(s) INDIGATE NATUR DENOTING REPORTS OF BUILDING REPORTS OF BUILDING NATUR DENOTING REPORTS OF BUILDING REPORTS OF BUI				
TYPE OS SUBMISSION Alter Casing Fracture Treat TRECEMENTION		Well Integrity		
✓ Subsequent Report ☐ Casing Repair ☐ New Construction ☐ Recomplete ✓ Other				
Final Abandonment Notice Change Plans Plug and Abandon Temporarily Abandon Convert to Injection Plug Back Water Disposal				
Convert to Injection [ 1 hay back [ Water Disposal			Completion	
			Reports	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete honzontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)				
11/17/11 - 3/21/12			:	
MIRU Key WSU. Test csg & BOP to 3000 psi, held 15 mins. CO to PBTD 16,471'. CHC. TOC @ 3980'. RU & RIH w/ WL.				
Frac 17 stages (9146 - 16,456') w/ total: 1,893,200 20/40 white sd; 217,900 30/50 white sd; 625,100 40/70 white sd;				
80,000 10 mesh white sd and 80K gals 7.5% HCL. FWB. DO frac plugs & CHC to PBTD. RIH w/ pkr & set @ 8122'. RU &				
RIH w/ swab. Set jet pump. TOP.				
Accepted for record  NMOCD				
(Attachment)				
14 Thereby certify that the foregoing is true and correct				
Name Judy A. Barnett X8699				
Signed Aude Shrull Title Regulatory Specialist	Date	4/26/2	012	
This space for Federal or State Office use)				
Approved by Title	Date			
Conditions of approval, if any	•	·		
This to to to to consist notes, makes it a difficult or any person knowingly and williamy to make any department of agency of the online of dates any failed, network or readdment statements of representations to any makes				
within its junidiction				

\*See Instruction on Reverse Side



