


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-14
Revised March 17, 1995
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

01MB/216748367 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact Tracy Kidd
Address P. O. Box 250 Artesia, NM 88211		Telephone No. 575-513-062
Facility Name Cotton Draw 65 SWD		Facility Type Salt Water Disposal
Surface Owner	Mineral Owner	Lease No. <u>112*</u>

LOCATION OF RELEASE

30-015-10843

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>65 G</u>	2	25S	31E	1980	North	1980	East	Eddy

NATURE OF RELEASE

Type of Release Oil Spill	Volume of Release 35 bbls	Volume Recovered 35 bbls
Source of Release Spill over	Date and Hour of Occurrence 6/8/12, 8:48AM	Date and Hour of Discovery 6/8/12, 8:48AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos / BLM & Mike Bratcher / OCD	
By Whom? Tracy Kidd & Daniel Suniga	Date and Hour 6/8/12, 9:33AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

At the Cotton Draw 65 SWD, the gun barrel malfunctioned causing a 35 bbl oil spill, all kept within the line containment. All fluid was recovered.

Describe Area Affected and Cleanup Action Taken.*

At the Cotton Draw 65 SWD, the gun barrel malfunctioned causing a 35 bbl oil spill, all kept within the line containment. The Gun barrel was overloaded with fluid coming in and was not able to maintain amount of fluid being pushed out, this caused the tanks to fill up with produced water, pushing the oil over the top of the tank. A vacuum truck was called and all 35 bbl of oil were recovered. The produced water was then hauled off to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Gracie Bustamante</u>		OIL CONSERVATION DIVISION	
Printed Name: Gracie Bustamante		Signed By <u>Mike Bratcher</u> Approved by District Supervisor:	
Title: Field Adm Support		Approval Date: <u>JUN 13 2012</u>	Expiration Date:
Date: 06/08/12 Phone: (575) 746-5561		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
7/13/2012

2RP-1169