

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

MAY 17 2012

NMOCD ARTESIA

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nmlb 1215845535

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211		Telephone No. 575-748-5238
Facility Name Strawberry 7 Federal #2		Facility Type Oil Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE 30-015-32375

Unit Letter	Section 7	Township 19S	Range 31E	Feet from the 1300	North/South Line North	Feet from the 1750	East/West Line East	County Eddy
-------------	-----------	--------------	-----------	--------------------	------------------------	--------------------	---------------------	-------------

NATURE OF RELEASE

Type of Release Oil	Volume of Release 30 bbls	Volume Recovered 26 bbls
Source of Release Test Heater Vent Valve Malfunction	Date and Hour of Occurrence 05/11/12, 7:30 AM	Date and Hour of Discovery 05/11/12, 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM / Mike Bratcher, OCD/ Terry Gregston	
By Whom? Merle Lewis	Date and Hour 5/11/12, 9:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Upon Arrival at the Strawberry 7-2 Battery, Lease Operator discovered a 30 barrel spill that was all kept within containment.

Describe Area Affected and Cleanup Action Taken.*

Upon Arrival at the Strawberry 7-2 Battery, Lease Operator discovered a 30 barrel spill that was all kept within containment. The test heater vent valve malfunctioned in the middle of the night, causing the spill. This caused the heater to bypass gas to the oil stock tank and tank bubbled over through the thief hatch. The pressure blew out the gasket on the waterleg and sprayed the heater and ground around the area. Talon LPE was contacted to take samples & submit a clean up plan to BLM. — See COA below ↓

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Gracie Bustamante		OIL CONSERVATION DIVISION	
Printed Name: Gracie Bustamante		Approved by	Signed By Mike Bratcher
Title: Field Adm. Support	Approval Date: JUN 06 2012	Expiration Date:	
Date: 5/15/12 Phone: (575) 746-5561	Conditions of Approval:	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
7/6/2012

2004 2RP-1152