	State of N	ew Mexico	Form C-103
Office District I	Energy, Minerals ar	nd Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-015-33504
1301 W. Grand Ave., Artesia, NM 88210		ATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410		St. Francis Dr.	STATE FEE
District IV	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Teledyne 20
1. Type of Well: Oil Well X	Gas Well 🔲 Other	RECEIVED	8. Well Number 005
2. Name of Operator			9. OGRID Number
Chesapeake Operating, Inc. APR 1 1 2005			147179
3. Address of Operator P. O. Bo	x 11050	OCD-APTERIA	10. Pool name or Wildcat
	TX 79702-8050	······································	Harroun Ranch;Delaware, NE
4. Well Location			_
Unit Letter J:	1980feet from the	South line and 23	10feet from theline
Section 20	Township 23S	Range 29E	NMPM CountyEddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
2959 GR			
Pit or Below-grade Tank Application 🗋 or Closure 🗌			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING			
		I	
			Frac 🕅
			Frac X ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
 Describe proposed or composed or starting any proposed w or recompletion. 2-25-05 MIRU Gray WL. RIH see Brushy Canyon 5,542 - 5,562' @ 2 2-26-05 MIRU Cudd, acidize Upp bbls HCL, spot 200 gals HCL @ 5 03-01-05 MIRU BJ Frac Services w/22,000# Super LC 16/30, total p pg - 8 ppg. Swabbing. 3-04-05 RIH w/170 jts. tbg., circ p sx cmt on plug, test CIBP to 500#, 	ork). SEE RULE 1103. For et CIBP @ 6010' dump 2 sx of 2 spf, 22', 45 holes, 120 deg. ber Brushy Canyon 5,542' - 5 ,669'. POOH to 5,542', rev. , frac Upper Brushy Canyon brop 53,000#, ramp from 2 p pkr fluid. SITP 250#, RIH w run chart 30 mins, test good	state all pertinent details, ar r Multiple Completions: A cmt on plug. Test plug to 2 phasing w/ 3/18" csg. gun. 5,564' w/1500 gals 15% nel spot acid into tbg. set pkr, w/17,120 gals x-link Light v/swab. MIRU Gray WL. I, RIH w/170 jts. tbg. circ p	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion 2000# - OK. RU lubricator, Perforate Upper Fe 90/10 acid, drop 10 ball sealers per 5 load and pressure BS to 1000#. Swabbing. ning 27 and 31,000# 16/30 Brown sand, tail RIH w/5 1/2" CIBP set @ 5,482', dump 2 kr fluid.
 Describe proposed or composed or starting any proposed w or recompletion. 2-25-05 MIRU Gray WL. RIH se Brushy Canyon 5,542 - 5,562' @ 2 2-26-05 MIRU Cudd, acidize Upp bbls HCL, spot 200 gals HCL @ 5 03-01-05 MIRU BJ Frac Services w/22,000# Super LC 16/30, total p pg - 8 ppg. Swabbing. 3-04-05 RIH w/170 jts. tbg., circ p 	ork). SEE RULE 1103. For et CIBP @ 6010' dump 2 sx of 2 spf, 22', 45 holes, 120 deg. ber Brushy Canyon 5,542' - 5 ,669'. POOH to 5,542', rev. , frac Upper Brushy Canyon brop 53,000#, ramp from 2 p pkr fluid. SITP 250#, RIH w run chart 30 mins, test good	state all pertinent details, ar r Multiple Completions: A cmt on plug. Test plug to 2 phasing w/ 3/18" csg. gun. 5,564' w/1500 gals 15% nel spot acid into tbg. set pkr, w/17,120 gals x-link Light v/swab. MIRU Gray WL. I, RIH w/170 jts. tbg. circ p	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion 2000# - OK. RU lubricator, Perforate Upper Fe 90/10 acid, drop 10 ball sealers per 5 load and pressure BS to 1000#. Swabbing. ning 27 and 31,000# 16/30 Brown sand, tail RIH w/5 1/2" CIBP set @ 5,482', dump 2 kr fluid.
 Describe proposed or composed or starting any proposed w or recompletion. 2-25-05 MIRU Gray WL. RIH see Brushy Canyon 5,542 - 5,562' @ 2 2-26-05 MIRU Cudd, acidize Upp bbls HCL, spot 200 gals HCL @ 5 03-01-05 MIRU BJ Frac Services w/22,000# Super LC 16/30, total p pg - 8 ppg. Swabbing. 3-04-05 RIH w/170 jts. tbg., circ p sx cmt on plug, test CIBP to 500#, 	ork). SEE RULE 1103. For et CIBP @ 6010' dump 2 sx of spf, 22', 45 holes, 120 deg. per Brushy Canyon 5,542' - 5 ,669'. POOH to 5,542', rev. , frac Upper Brushy Canyon prop 53,000#, ramp from 2 p pkr fluid. SITP 250#, RIH w run chart 30 mins, test good " rods, LD 97 - 7/8" 8rd tbg.	state all pertinent details, ar r Multiple Completions: A cmt on plug. Test plug to 2 phasing w/ 3/18" csg. gun. 5,564' w/1500 gals 15% nel spot acid into tbg. set pkr, w/17,120 gals x-link Light y/swab. MIRU Gray WL. I, RIH w/170 jts. tbg. circ p . Temporarily Abandon. R	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion 2000# - OK. RU lubricator, Perforate Upper Fe 90/10 acid, drop 10 ball sealers per 5 load and pressure BS to 1000#. Swabbing. ning 27 and 31,000# 16/30 Brown sand, tail RIH w/5 1/2" CIBP set @ 5,482', dump 2 kr fluid. 2DMO
 Describe proposed or composed or starting any proposed w or recompletion. 2-25-05 MIRU Gray WL. RIH see Brushy Canyon 5,542 - 5,562' @ 2 2-26-05 MIRU Cudd, acidize Upp bbls HCL, spot 200 gals HCL @ 5 03-01-05 MIRU BJ Frac Services w/22,000# Super LC 16/30, total p pg - 8 ppg. Swabbing. 3-04-05 RIH w/170 jts. tbg., circ p sx cmt on plug, test CIBP to 500#, 3-05-05 RIH w/ 7/8" rods and 3/4 	ork). SEE RULE 1103. For et CIBP @ 6010' dump 2 sx of spf, 22', 45 holes, 120 deg. per Brushy Canyon 5,542' - 5 ,669'. POOH to 5,542', rev. , frac Upper Brushy Canyon prop 53,000#, ramp from 2 p pkr fluid. SITP 250#, RIH w run chart 30 mins, test good " rods, LD 97 - 7/8" 8rd tbg.	state all pertinent details, ar r Multiple Completions: A cmt on plug. Test plug to 2 phasing w/ 3/18" csg. gun. 5,564' w/1500 gals 15% nel spot acid into tbg. set pkr, w/17,120 gals x-link Light y/swab. MIRU Gray WL. I, RIH w/170 jts. tbg. circ p . Temporarily Abandon. R	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion 2000# - OK. RU lubricator, Perforate Upper Fe 90/10 acid, drop 10 ball sealers per 5 load and pressure BS to 1000#. Swabbing. ning 27 and 31,000# 16/30 Brown sand, tail RIH w/5 1/2" CIBP set @ 5,482', dump 2 kr fluid. 2DMO
 Describe proposed or composed of starting any proposed w or recompletion. 2-25-05 MIRU Gray WL. RIH see Brushy Canyon 5,542 - 5,562' @ 2 2-26-05 MIRU Cudd, acidize Upp bbls HCL, spot 200 gals HCL @ 5 03-01-05 MIRU BJ Frac Services w/22,000# Super LC 16/30, total p pg - 8 ppg. Swabbing. 3-04-05 RIH w/170 jts. tbg., circ p sx cmt on plug, test CIBP to 500#, 3-05-05 RIH w/ 7/8" rods and 3/4 Per letter of 3/16/05 from OCD with the second start of the seco	ork). SEE RULE 1103. For et CIBP @ 6010' dump 2 sx of spf, 22', 45 holes, 120 deg. ber Brushy Canyon 5,542' - 5 ,669'. POOH to 5,542', rev. , frac Upper Brushy Canyon brop 53,000#, ramp from 2 p pkr fluid. SITP 250#, RIH w run chart 30 mins, test good " rods, LD 97 - 7/8" 8rd tbg. Il call with 24 hour notice ar	state all pertinent details, ar r Multiple Completions: A cmt on plug. Test plug to 2 phasing w/ 3/18" csg. gun. 5,564' w/1500 gals 15% nel spot acid into tbg. set pkr, w/17,120 gals x-link Light w/swab. MIRU Gray WL. I, RIH w/170 jts. tbg. circ p . Temporarily Abandon. R nd retest the well. Chart to	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion 2000# - OK. RU lubricator, Perforate Upper Fe 90/10 acid, drop 10 ball sealers per 5 load and pressure BS to 1000#. Swabbing. ning 27 and 31,000# 16/30 Brown sand, tail RIH w/5 1/2" CIBP set @ 5,482', dump 2 kr fluid. 2DMO

SIGNATURE Dented Of

TITLE Regulatory Analyst

DATE 04/05/2005 Telephone No. (432)687-2992

Type or print name Brenda Coffman **For State Use Only**

E-mail address:bcoffman@chkenergy.com



APPROVED BY: _____ Conditions of Approval (if any): TITLE

ASSER

0.000