Submit 3 Copies To Appropriate District	State of New Mex	ico	Form C-103
Office District I	Energy, Minerals and Natura	al Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240		WE	LL API NO.
District II	OH CONCERNATION	30-4	015-33741
OIL CONSERVATION DIVISION OIL CONSERVATION DIVISION		1 7 1	Indicate Type of Lease
strict III 1220 South St. Francis Dr.		eis Dr.	STATE S FEE
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 875	505	State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Juliu 1 0, 1 11/1 0 / 0	U. K	State Off & Gas Lease 140.
87505			
	AND REPORTS ON WELLS	7.]	Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			rgan State
DIFFERENT RESERVOIR. USE "APPLICATIO	N FOR PERMIT" (FORM C-101) FOR		
PROPOSALS.)		8 7	Well Number
1. Type of Well:	RE	CEIVED #1	VV 011 TVUINIOUS
Oil Well Gas Well Other	er	"1	
2. Name of Operator	AP	R 0 6 2005 9. 0	OGRID Number
Nadel and Gussman Permian, LLC	OCI	SOPTEGIA 155	
3. Address of Operator	<u></u>		Pool name or Wildcat
601 N. Marienfeld Suite 508 Midland, T	evas 79701		ton Flat (Morrow) 73280
	CABS 77701		(WILL (WILL) 75200
4. Well Location			
Unit Letter A: 660'feet	from the North line and	660'feet from t	the Eastline
	p 21-S Range 27-E		County Eddy
11.	Elevation (Show whether DR, I	RKB, RT, GR, etc.)	The state of the s
327	79'	,	
Pit or Below-grade Tank Application (For pit or		-144 must be attached)	And the state of t
			A 6
Pit Location: UL A_Sect 16_Twp 21-S_R			
Distance from nearest surface water 1000'+	Below-grade Tank Location UL	SectTwp	Rng ;
feet from theline and	feet from the line		
12 Check Appro	onrigte Roy to Indicate Na	ture of Notice Reno	ort or Other Data
	opriate Box to Indicate Na		
NOTICE OF INTEN	NTION TO:	SUBSEC	QUENT REPORT OF:
	NTION TO:		
NOTICE OF INTEN	NTION TO: UG AND ABANDON	SUBSEQ REMEDIAL WORK	QUENT REPORT OF: ALTERING CASING
NOTICE OF INTEN	NTION TO: UG AND ABANDON	SUBSEC	QUENT REPORT OF: ALTERING CASING GOPNS. PLUG AND
NOTICE OF INTENPERFORM REMEDIAL WORK PLI	NTION TO: UG AND ABANDON ANGE PLANS	SUBSEC REMEDIAL WORK COMMENCE DRILLING	QUENT REPORT OF: ALTERING CASING GOPNS. PLUG AND ABANDONMENT
NOTICE OF INTENPERFORM REMEDIAL WORK PLUT TEMPORARILY ABANDON CH	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE	SUBSECT REMEDIAL WORK COMMENCE DRILLING CASING TEST AND	QUENT REPORT OF: ALTERING CASING GOPNS. PLUG AND
NOTICE OF INTENPERFORM REMEDIAL WORK PLUT TEMPORARILY ABANDON CH	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE	SUBSEC REMEDIAL WORK COMMENCE DRILLING	QUENT REPORT OF: ALTERING CASING GOPNS. PLUG AND ABANDONMENT
NOTICE OF INTEN PERFORM REMEDIAL WORK PLI TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE DMPLETION	SUBSECT REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB	QUENT REPORT OF: ALTERING CASING BOPNS. PLUG AND ABANDONMENT
NOTICE OF INTEN PERFORM REMEDIAL WORK PLI TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER:	NTION TO: UG AND ABANDON ANGE PLANS ULTIPLE MPLETION	SUBSECT REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Rep	QUENT REPORT OF: ALTERING CASING GOPNS. PLUG AND ABANDONMENT DOIT POORT DOIT
NOTICE OF INTEN PERFORM REMEDIAL WORK PLI TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER: 13. Describe proposed or completed	ITION TO: UG AND ABANDON ANGE PLANS ILTIPLE MPLETION operations. (Clearly state all po	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Reportment details, and give	QUENT REPORT OF: ALTERING CASING BY OPNS. PLUG AND ABANDONMENT Port Port Pertinent dates, including estimated date
NOTICE OF INTEN PERFORM REMEDIAL WORK PLI TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER: 13. Describe proposed or completed	ITION TO: UG AND ABANDON ANGE PLANS ILTIPLE MPLETION operations. (Clearly state all po	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Reportment details, and give	QUENT REPORT OF: ALTERING CASING BY OPNS. PLUG AND ABANDONMENT Port Port Pertinent dates, including estimated date
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER: 13. Describe proposed or completed of starting any proposed work).	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE OMPLETION Operations. (Clearly state all po	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Reportment details, and give	QUENT REPORT OF: ALTERING CASING GOPNS. PLUG AND ABANDONMENT DOI: D
NOTICE OF INTEN PERFORM REMEDIAL WORK PLI TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER: 13. Describe proposed or completed	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE OMPLETION Operations. (Clearly state all possessed RULE 1103. For Multiple	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Reportment details, and give	QUENT REPORT OF: ALTERING CASING BY OPNS. PLUG AND ABANDONMENT Port Port Pertinent dates, including estimated date
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110	ITION TO: UG AND ABANDON ANGE PLANS ILTIPLE MPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'.	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Reportment details, and gives Completions: Attach v	QUENT REPORT OF: ALTERING CASING BY ALTERING CASING BY ABANDONMENT ABANDONMENT Composed completion Composed completion
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110) 03/31/05 Cement 1stage 1,510 sx of PVL w/ gas in the proposed work.	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE DMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertment details, and give completions: Attach vivor 271bbls bump plug @ 10:	QUENT REPORT OF: ALTERING CASING BY ALTERING CAS
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1 st stage 1,510 sx of PVL w/ gas I Cement 2 nd stage Lead1,300sx litecrete and tail 200:	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE DMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wat	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertment details, and give completions: Attach vivor 271bbls bump plug @ 10:	QUENT REPORT OF: ALTERING CASING BY ALTERING CAS
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110) 03/31/05 Cement 1stage 1,510 sx of PVL w/ gas in the proposed work.	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE DMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wat	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertment details, and give completions: Attach vivor 271bbls bump plug @ 10:	QUENT REPORT OF: ALTERING CASING BY ALTERING CAS
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU CO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1 st stage 1,510 sx of PVL w/ gas I Cement 2 nd stage Lead1,300sx litecrete and tail 200:	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE DMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wat	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertment details, and give completions: Attach vivor 271bbls bump plug @ 10:	QUENT REPORT OF: ALTERING CASING BY ALTERING CAS
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1st stage 1,510 sx of PVL w/ gas 1 Cement 2st stage Lead1,300sx litecrete and tail 200 st tubing head test @ 5,000 psi. Run temp survey cem	ITION TO: UG AND ABANDON ANGE PLANS ULTIPLE OMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface.	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give completions: Attach v w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips v	QUENT REPORT OF: ALTERING CASING BY ALTERING CASING BY ABANDONMENT ABANDONMENT CONTROL CO
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1st stage 1,510 sx of PVL w/ gas 1 Cement 2st stage Lead1,300sx litecrete and tail 200 st tubing head test @ 5,000 psi. Run temp survey cem	ATION TO: UG AND ABANDON ANGE PLANS DITIPLE OMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface.	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give completions: Attach v w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips v t of my knowledge and	QUENT REPORT OF: ALTERING CASING BY ALTERING CASING BY ABANDONMENT ABANDONMENT CONTROL CO
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1st stage 1,510 sx of PVL w/ gas 1 Cement 2st stage Lead1,300sx litecrete and tail 200 st tubing head test @ 5,000 psi. Run temp survey cem	ATION TO: UG AND ABANDON ANGE PLANS DITIPLE OMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface.	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give completions: Attach v w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips v t of my knowledge and	QUENT REPORT OF: ALTERING CASING BY ALTERING CASING BY ABANDONMENT ABANDONMENT CONTROL CO
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1st stage 1,510 sx of PVL w/ gas 1 Cement 2st stage Lead1,300sx litecrete and tail 200 st tubing head test @ 5,000 psi. Run temp survey cem I hereby certify that the information above grade tank has been/will be constructed or closed	ATION TO: UG AND ABANDON ANGE PLANS DETIPLE DIAMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface.	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and gives Completions: Attach v w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips v t of my knowledge and a general permit or an or	QUENT REPORT OF: ALTERING CASING ALTER
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1st stage 1,510 sx of PVL w/ gas 1 Cement 2st stage Lead1,300sx litecrete and tail 200 st tubing head test @ 5,000 psi. Run temp survey cem	ATION TO: UG AND ABANDON ANGE PLANS DITIPLE OMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface.	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and gives Completions: Attach v w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips v t of my knowledge and a general permit or an or	QUENT REPORT OF: ALTERING CASING ALTER
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1stage 1,510 sx of PVL w/ gas Cement 2stage Lead1,300sx litecrete and tail 200 stubing head test \$\tilde{\theta}\$ 5,000 psi. Run temp survey cem I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE	ATION TO: UG AND ABANDON ANGE PLANS ULTIPLE OMPLETION Operations. (Clearly state all posses RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface. e is true and complete to the best according to NMOCD guidelines TITLE	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give Completions: Attach vor w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips vor t of my knowledge and a general permit or an of Staff Engineer	QUENT REPORT OF: ALTERING CASING CASING CASING AND ABANDONMENT Port ABANDONMENT P
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1st stage 1,510 sx of PVL w/ gas 1 Cement 2st stage Lead1,300sx litecrete and tail 200 st tubing head test @ 5,000 psi. Run temp survey cem I hereby certify that the information above grade tank has been/will be constructed or closed	ATION TO: UG AND ABANDON ANGE PLANS ULTIPLE OMPLETION Operations. (Clearly state all posses RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface. e is true and complete to the best according to NMOCD guidelines TITLE	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give Completions: Attach vor w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips vor t of my knowledge and a general permit or an of Staff Engineer	QUENT REPORT OF: ALTERING CASING ALTER
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1stage 1,510 sx of PVL w/ gas Cement 2stage Lead1,300sx litecrete and tail 200 stubing head test \$\tilde{\theta}\$ 5,000 psi. Run temp survey cem I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE	ATION TO: UG AND ABANDON ANGE PLANS ULTIPLE OMPLETION Operations. (Clearly state all posses RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface. e is true and complete to the best according to NMOCD guidelines TITLE	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give Completions: Attach vor w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips vor t of my knowledge and a general permit or an of Staff Engineer	QUENT REPORT OF: ALTERING CASING CASING CASING AND ABANDONMENT Port ABANDONMENT P
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1stage 1,510 sx of PVL w/ gas Cement 2stage Lead1,300sx litecrete and tail 200 stubing head test \$\tilde{\theta}\$ 5,000 psi. Run temp survey cem I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE	ATION TO: UG AND ABANDON ANGE PLANS ULTIPLE OMPLETION Operations. (Clearly state all posses RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface. e is true and complete to the best according to NMOCD guidelines TITLE	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give Completions: Attach vor w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips vor t of my knowledge and a general permit or an of Staff Engineer	QUENT REPORT OF: ALTERING CASING CASING CASING AND ABANDONMENT Port ABANDONMENT P
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1 st stage 1,510 sx of PVL w/ gas cement 2 nd stage Lead1,300sx litecrete and tail 200 tubing head test @ 5,000 psi. Run temp survey cem I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name Josh Fernau	ATION TO: UG AND ABANDON ANGE PLANS ULTIPLE OMPLETION Operations. (Clearly state all posses RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface. e is true and complete to the best according to NMOCD guidelines TITLE	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give Completions: Attach vor w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips vor t of my knowledge and a general permit or an of Staff Engineer	QUENT REPORT OF: ALTERING CASING CASING CASING AND ABANDONMENT Port ABANDONMENT P
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1st stage 1,510 sx of PVL w/ gas 1 Cement 2st stage Lead1,300sx litecrete and tail 200 st tubing head test \$\tilde{\textit{@}}\$ 5,000 psi. Run temp survey cem I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Furname Josh Fernau (This space for State use)	ATION TO: UG AND ABANDON ANGE PLANS ULTIPLE OMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417'. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface. e is true and complete to the best according to NMOCD guidelines TITLE E-mail address: jos	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give Completions: Attach vor w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips vor t of my knowledge and a general permit or an of Staff Engineer	QUENT REPORT OF: ALTERING CASING AND ABANDONMENT ALTERING CASING SITUATION AND ABANDONMENT ALTERING CASING AND ABANDON ALTERING CASING AND ALTERING C
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 03/30/05 Rig up and run 5.5 casing (17# S/P 110 03/31/05 Cement 1 st stage 1,510 sx of PVL w/ gas cement 2 nd stage Lead1,300sx litecrete and tail 200 tubing head test @ 5,000 psi. Run temp survey cem I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name Josh Fernau	ATION TO: UG AND ABANDON ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all pose SEE RULE 1103. For Multiple 273 jts w/ DV too @ 7,417. block (382 BBLs @ 13 ppg). Displace sx PVL displaced w/ 173bbls fresh wate ent 35' from surface. e is true and complete to the best according to NMOCD guidelines TITLE E-mail address: jos	SUBSEC REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: Amended Repertinent details, and give Completions: Attach vor w/ 271bbls bump plug @ 10: er @ 4:50 pm. N/D set slips vor t of my knowledge and a general permit or an of Staff Engineer	QUENT REPORT OF: ALTERING CASING CASING CASING AND ABANDONMENT Port ABANDONMENT P