Office	State of New Me	XICO	Form C-10	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised August 1, 20 WELL API NO.	)11
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	7/9_1092		30-015-38528	
811 S. First St, Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd, Aztec, NM 87410	1220 South St. Francis Dr.		STATE STATE	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87	/505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr, Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	•
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		Diamondback 22 State Com		
1. Type of Well: Oil Well  Gas Well  Other			8. Well Number	
2. Name of Operator			9. OGRID Number	
COG Production LLC  3. Address of Operator		217955 10. Pool name or Wildcat		
2208 W. Main Street, Artesia, NM 88210		Hay Hollow; Bone Spring		
4. Well Location			Tray Trene w, Bene Spring	
Unit Letter B	:480 feet from theNor	th line and	1960 feet from the East line	
Section 22	<del></del>	Range 28E	NMPM Eddy County	
	11. Elevation (Show whether DR,	0		
	2981'	GR		
G1 1		22.7		
12. Check	Appropriate Box to Indicate Na	ature of Notice,	Report or Other Data	
NOTICE OF II	NTENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOF				
TEMPORARILY ABANDON		COMMENCE DRI	ILLING OPNS. 🗌 PAND A	
PULL OR ALTER CASING	<b>—</b>	CASING/CEMEN	T JOB	
DOWNHOLE COMMINGLE				
OTHER:		OTHER: [	Drill Out Frac Plugs	$\operatorname{A}$
OTHER:  13. Describe proposed or com	pleted operations. (Clearly state all p	pertinent details, and	Orill Out Frac Plugs d give pertinent dates, including estimated of	<u>⊠</u> date
OTHER:  13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC	pertinent details, and		⊠_ date
OTHER:  13. Describe proposed or com	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC	pertinent details, and	d give pertinent dates, including estimated	⊠_ date
OTHER:  13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC	pertinent details, and	d give pertinent dates, including estimated	⊠_ date
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	pertinent details, and C. For Multiple Con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of	⊠_ date
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	pertinent details, and C. For Multiple Con	d give pertinent dates, including estimated	⊠ date
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	pertinent details, and C. For Multiple Con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of	⊠_ date
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	pertinent details, and C. For Multiple Cor	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of	⊠ date
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	pertinent details, and C. For Multiple Cor	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'	<u>⊠</u> date
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	pertinent details, and C. For Multiple Cor	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'	date
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.	pertinent details, and C. For Multiple Cor	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7 & pkr @ 7840'. Placed on gas lift	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  FOOH w/tbg & pkr. Drilled out all Consystem.	pertinent details, and C. For Multiple Con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. The second of the seco	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  FOOH w/tbg & pkr. Drilled out all Cosystem.	pertinent details, and C. For Multiple Con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012  NMOCD ARTESIA	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7 & pkr @ 7840'. Placed on gas lift	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  FOOH w/tbg & pkr. Drilled out all Consystem.	pertinent details, and C. For Multiple Con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012  NMOCD ARTESIA	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7 & pkr @ 7840'. Placed on gas lift.  Spud Date:  2/16/1	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  FOOH w/tbg & pkr. Drilled out all Consystem.	certinent details, and c. For Multiple Con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012  NMOCD ARTESIA	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7 & pkr @ 7840'. Placed on gas lift.  Spud Date:  2/16/1	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  FOOH w/tbg & pkr. Drilled out all Consystem.	certinent details, and c. For Multiple Con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012  NMOCD ARTESIA	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. The second of the starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. The second of the seco	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  TOOH w/tbg & pkr. Drilled out all Consystem.  Rig Release Date above is true and complete to the beautiful or	certinent details, and continued con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012  NMOCD ARTESIA  3/19/12	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. 7 & pkr @ 7840'. Placed on gas lift.  Spud Date:  2/16/1	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  TOOH w/tbg & pkr. Drilled out all Consystem.  Rig Release Date above is true and complete to the beautiful or	certinent details, and c. For Multiple Con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012  NMOCD ARTESIA	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. The second of the starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. The second of the seco	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  COOH w/tbg & pkr. Drilled out all Cosystem.  Rig Release Date above is true and complete to the beautiful above is true and complete to the beautiful above.	certinent details, and continued con	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012  NMOCD ARTESIA  3/19/12  e and belief.  DATE: 6/29/12	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. The second of the starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. The second of the seco	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  COOH w/tbg & pkr. Drilled out all Cosystem.  Rig Release Date above is true and complete to the beautiful above is true and complete to the beautiful above.	certinent details, and c. For Multiple Con CFP's. Circulated classes.	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012  NMOCD ARTESIA  3/19/12  e and belief.  DATE: 6/29/12	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. Take pkr @ 7840'. Placed on gas lift to the pkr @ 7840'. Placed on gas lift to the pkr @ 7840'. Placed on gas lift to the pkr @ 7840'. Thereby certify that the information SIGNATURE Type or print name: Stormi Date For State Use Only	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  COOH w/tbg & pkr. Drilled out all Cosystem.  Rig Release Date above is true and complete to the beautiful above is true and complete to the beautiful above.	certinent details, and c. For Multiple Con CFP's. Circulated classes.	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of mpletions: Attach wellb	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  6/22/12 to 6/28/12 MIRU WSU. T & pkr @ 7840'. Placed on gas lift  Spud Date:  2/16/1  I hereby certify that the information  SIGNATURE  Type or print name: Stormi Date	pleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC completion.  COOH w/tbg & pkr. Drilled out all Cosystem.  Rig Release Date above is true and complete to the beautiful above is true and complete to the beautiful above.	certinent details, and c. For Multiple Con CFP's. Circulated classes.	d give pertinent dates, including estimated of mpletions: Attach wellbore diagram of lean. Set 2 7/8" 6.5# L-80 tbg @ 7847'  RECEIVED  JUL 0 3 2012  NMOCD ARTESIA  3/19/12  e and belief.  DATE: 6/29/12	