

Submit 1 Copy To Appropriate District Office  
District I – (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II – (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III – (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV – (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised August 1, 2011

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-23815
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Alamo Permian Resources, LLC		6. State Oil & Gas Lease No. NM 703-69
3. Address of Operator 415 W. Wall Street, Suite 500, Midland, TX 79701		7. Lease Name or Unit Agreement Name DONNELLY KELLY ST
4. Well Location Unit Letter O : 990 feet from the S line and 2270 feet from the E line Section 8 Township 18S Range 28E NMPM County EDDY		8. Well Number 3
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 274841
		10. Pool name or Wildcat RED LAKE; Q/GRYBG/SAN ANDRES

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: RETURN TO PRODUCTION ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06/30/12

MIRU. POOH with (4) 3/4" subs= 2'-4'-6'-8', (95) 3/4" rods, & pump. ND WH, NU BOP. SDFN.

07/02/12

RIH, tag @ 2510'. POOH with 63 jts 2 3/8" tbg, 4 1/2"x2 3/8" TAC, 13 jts 2 3/8" tbg, 1 SN, (1) 2 3/8"x15' mule shoe. SWI. SDFN.

07/03/12

RIH with 2 3/8"x15' mule shoe, (1) 2 3/8" SN, & 13 jts 2 3/8" tbg. Found hole on 13<sup>th</sup> joint & above SN. Ran 1 enduro jt above SN then 12 jts to 4 1/2"x2 3/8" TAC, 63 jts 2 3/8" tbg. ND BOP. Set TAC. SN @ 2461'. Test to 5000 PSI, tagged @ 2510'. NU WH. RIH with (95) 3/4" rods, (4) 3/4" subs: 2'-4'-6'-8', & pump. Checked pump action, was good. SDFN.

Spud Date:

Rig Release Date:

RECEIVED

JUL 16 2012

NMOCD ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Tom Fulvi*

TITLE Regulatory Affairs Coordinator

DATE: 07/13/2012

Type or print name

Tom Fulvi

E-mail address: tfulvi@alamoresources.com

PHONE: 432.897.0673

APPROVED BY:

*RDale*

TITLE Dist. Rep. Supervisor

DATE 7/18/12

Conditions of Approval (if any):