<u>District I</u>
1625 N. French Dr., Hobbs, NM 88240
<u>District II</u>
1301 W. Grand Avenue, Artesia, NM 88210
<u>District III</u>
1000 Rio Brazos Road, Aztec, NM 87410
<u>District IV</u>
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Rel	ease Notific	atio	n and Co	rrective	e Acı	tion			
		13469	73		OPERA	TOR		🛛 Ini	tial Report	Final Repo		
Name of Co		Contact Tony Savoie										
Address 52 Facility Na		Telephone No. 432-556-8730 Facility Type E&P										
			CΠ #143									
Surface Ow	vner Federa	al	<u>`</u>	Mineral C	ederal Lease No.							
				LOCA	N OF RELEASE 30-0/5-3/4/6							
Unit Letter I	Section 31	Township 23S	Range 30E	Feet from the	North	South Line	Feet from t	he F	East/West Line	County Eddy		
Latitude_N 32.260954 Longitude W 103.914777												
Type of Release: Produced water and crude oil NATURE OF RELEASE Volume of Release: 30 Bbls of Volume Recovered: None												
Type of Release. Froduced water and crude off						Produced water and 15 Bbls crude oil				, Recovered. None		
Source of Release: 2 7/8" flow line										and Hour of Discovery 12 2:00 p.m.		
Was Immedi	If YES, To Whom?											
☐ Yes ☐ No ☐ Not Required NMOCD Mike Bratcher and BLM Jim Amos												
By Whom? Tony Savoie						Date and Hour 6/1/12, NMOCD at 11:42 a.m. BLM at 11:45 a.m. The report was delayed to a medical situation with T.S.						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No							RECEIVED					
If a Watercou		JUÑ 26 2012					į.					
							NMOCD ARTESIA					
Describe Cause of Problem and Remedial Action Taken.* The flow line developed a leak due to external corrosion. A temporary repair clamp was placed on the pipe. Four joints of pipe were replaced between 5/30/12 and 6/14/12.												
Describe Area Affected and Cleanup Action Taken.* Approximately 2000 sq. ft. of pasture land. All of the released fluid soaked into the ground. The spill												
happened on top of an area previously impacted by at least 2 prior flow line releases. There is also an area in the impact zone that has exposed plastic from a reserve pit location. The release site will be reviewed with the BLM and NMOCD to determine the best course of action. The remediation will comply with the NMOCD and BLM requirements for spills.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
rederal, state,	or tocal taw	3 and or regul	ations.		T		OIL CO	NSE	RVATION	DIVISION	V	
Signature: Jong Saulu A						OIL CONSERVATION DIVISION Approved by District Supervisor: Signed By						
												Printed Name:
Title: Waste Mgmt. & Remediation Specialist						JUL 1 1 2012 Expiration Date:						
E-mail Addres	s: TASavoi	e@BassPet.co	m		c	onditions of A	Approval:					
Date: 6/24/12			F	Phone:432-556-87	30					Attached	□	
Attach Additi		Remediation per OCD Rules & 2RP-1206										

Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: