


NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input type="checkbox"/>
LAND OFFICE	<input type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>



Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.
30-005-60434

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator TXO Production Corp. ✓	8. Farm or Lease Name O'Brien "B" C
3. Address of Operator 900 Wilco Bldg. Midland, TX 79701	9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 9-S RANGE 29-E NMPM.	10. Field and Pool, or Wildcat Uncl. (Strawn)
15. Elevation (Show whether DF, RT, CR, etc.) 3980.8GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-24-85 Rlsd. pkr. TOH. Pu CIBP. TIG Set CIBP @8500' W/35' cmt on top.
8-25-85 SI for Sunday
8-26-85 TIH. Spt 25sx "C" plug @7378. TOH. Set 25sx "C" plug @6861. Set 25sx "C" plug @6136
8-27-85 Set 45sx "C" plug @4674.
8-28-85 TIH. Tag cmt @4572. Set 25sx "C" plug @3804. Set 35sx "C" plug @2678. Tag cmt plug @2566. Set 25sx "C" plug @357. Removed WH. Cmt surface w/25sx "C" plug
Install dryhole mrkr. Well P & A'd

Post ID-2
9-13-85
P+A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cilicia Henderson TITLE Engr. Asst. DATE 9-5-85

APPROVED BY Darrell Moore TITLE Geologist DATE 12/2/85
CONDITIONS OF APPROVAL, IF ANY: