

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

AUG 23 2012

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form
NMOCD ARTESIA

Release Notification and Corrective Action

nJMW/217254/25

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian	Contact	Chris Jones
Address	1502 W. Commerce Drive	Telephone No.	575-449-3337
Facility Name	Parakeet 29 Battery	Facility Type	Gathering

Surface Owner	Mineral Owner	Lease No.	AAZ 30-015-35140
---------------	---------------	-----------	------------------

LOCATION OF RELEASE *Parakeet 29 Fed #1*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	29	19S	27E	1535	S	662	E	Eddy County, NM

Latitude N 32.62853 Longitude W 104.29463

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	5 bbls	Volume Recovered	0 bbls
Source of Release	Load line failure	Date and Hour of Occurrence	4/24/12 @ 8:00 am	Date and Hour of Discovery	4/24/12 @ 2:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD; Jennifer Van Curen-BLM		
By Whom?	Leslie Moreno	Date and Hour	4/25/12 @ 8:00 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A load line rupture caused 5 bbls of condensate to spill onto the ground. Recovery was not possible due to evaporation. No remediation was needed because this battery is lined with a plastic liner.

Describe Area Affected and Cleanup Action Taken.*

The area affected was contained in the lined battery. No remediation was needed because this battery is lined with a plastic liner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Chris Jones

Title: HES Specialist

E-mail Address: Christopher.Jones@oxy.com

Date: 08/23/2012

Phone: (575) 449-3337

Signed By *Mike Bratcher*

Approved by District Supervisor:

AUG 24 2012

Approval Date:

Expiration Date: *N/A*

Conditions of Approval: *MA*

Attached ☐

* Attach Additional Sheets If Necessary

2RP-1178