Form 3160-5 (September 2001)

3a Address

1. Type of Well Oil Well □

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OM B No 1004-0135

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

Other

Gas Well □□

2 Name of Operator AMERICO ENERGY RESOURCES, LLC

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

7575 SAN FELIPE ST. STE 200 Houston, TX 77063

K - Sec. 34 - 18S - 31E 2310 FWL and 1650 FSL

Expires January 31, 2004	
5. Lease Serial No.	
NM-NM-10190	

If Indian, Allottee or Tribe Name

N/A
7. If Unit or CA/Agreement, Name and/or No.
8910115720
8. Well Name and No.
East Shugart Unit #17
9. API Well No.
30-015-05686

3b. Phone No. (include area code) 713-984-9700 10. Field and Pool, or Exploratory Area Shugart (Y-SR-Q-G-) 11. County or Parish, State

Eddy, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity Other

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

MIRUWOR, POH W/ RODS & TBING, RIH W/ BIT & SCRAPPER CLEAN OUT TO PBTD @ 3892', POH W/ TBING, L/D BIT & SCRAPPER, RIH W/ PRODUCTION TBING, FLANGE UP WELLHEAD, RIH W/ PUMP & ROD STRING, HANG WELL ON AND RETURN TO PRODUCTION.

RECEIVED

AUG 24 2012

NMOCD ARTES:

SEE ATTACHED FOR CONDITIONS OF APPROVAL COA PAR 08/06/2012

14. 1 hereby certify that the foregoing is true and correct Name (Printed/Typed)	
Ehsan Bayat	e Regulatory Analyst
Signature Dat	te 05/30/2012
THIS SPACE FOR FEDERAL OF	R STATE OFFICE USE
Approved by /s/ JD Whitlock Jr	Title LRET Date 8/22/12
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office (FO
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person	on knowingly and willfully to make to any department or agency of the U

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Conditions of Approval

Americo Energy Resources, LLC East Shugart Unit - 017 API 3001505686 August 06, 2012

This well's recorded activity has been inactive/shut-in for more than 30 days without authorization. An inactive/shut-in well bore is a non-producing completion that is capable of production in **paying quantities** or of service use.

1. As the current operator you are required to: Prove the production casing integrity from no more than 100 feet above the perforations or open hole with a BLM witnessed documented minimum pressure test of 500psig for 30 minutes. Notify BLM 575-361-2822 Eddy Co. before test procedures. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.

Also do one of the following:

- A) Return the well to production or beneficial use on or before 11/06/2012.
- B) Submit a plan for BLM plug and abandonment status approval of the well on or before 11/06/2012.

Determine the operational value and condition this well based on that value. Submit your plan for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies) with your committed timetable for accomplishment.

A legitimate request is necessary for extension of that date.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.