

RECEIVED  
District I  
625 N. French Dr., Hobbs, NM 88240  
District II: AUG 20 2012  
811 S First St., Artesia, NM 88210  
District III  
100 Rio Brazos Parkway, Santa Fe, NM 87505  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-129  
Revised August 1, 2011

Submit one copy to appropriate  
District Office

NFO Permit No. \_\_\_\_\_  
(For Division Use Only)

APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12

(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)

- A. Applicant Cimarex Energy Co. of Colorado 30-015-38323  
whose address is 600 N Marienfeld St Suite 600 Midland TX 79701,  
hereby requests an exception to Rule 19.15.18.12 for 30 days beginning 7-19-2012 or until  
DCP pipeline is repaired, Yr 2012, for the following described tank battery (or LACT):  
Name of Lease Mayaro 22 State #3 Name of Pool Empire; Glorieta-Yeso, East  
Location of Battery: Unit Letter I Section 22 Township 17S Range 29E  
Number of wells producing into battery 1
- B. Based upon oil production of 80 barrels per day, the estimated \* volume  
of gas to be flared is 112 MCF; Value \$224 per day.
- C. Name and location of nearest gas gathering facility:  
\_\_\_\_\_
- D. Distance \_\_\_\_\_ Estimated cost of connection \_\_\_\_\_
- E. This exception is requested for the following reasons: To Artesia, shut down for pipeline repair.  
Estimated repairs 8 to 10 days

OPERATOR

I hereby certify that the rules and regulations of the Oil Conservation  
Division have been complied with and that the information given above  
is true and complete to the best of my knowledge and belief.

Signature \_\_\_\_\_

Printed Name

& Title: Chloe Alexander, Regulatory Admin Assistant

E-mail Address: cdalexander@cimarex.com

Date 8-17-12

Telephone No. 432-620-1938

OIL CONSERVATION DIVISION

Approved Until Sept 30-2012

By RDade

Title Dist R Supervisor

Date 8/29/2012

\* Gas-Oil ratio test may be required to verify estimated gas volume.