

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB No 1004-0137
Expires July 31, 2010RECEIVED
AUG 29 2012
NMOCD ARTESIAREGULATORY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other Instructions on page 2.

1 Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5 Lease Serial No NMNM057239
2 Name of Operator COG Operating LLC	6 If Indian, Allottee, or Tribe Name
3a Address 2208 W. Main Street Artesia, NM 88210	7 If Unit or CA Agreement Name and/or No
3b Phone No (include area code) 575-748-6946	8 Well Name and No Lizard Pot Federal Com #3H
4 Location of Well (Footage, Sec, T, R, M., or Survey Description) 1650' FSL & 2310' FEL, Unit J (NWSE) Sec 36-T19S-R31E	9 API Well No 30-015-38147
Lat. Long.	10 Field and Pool, or Exploratory Area WC Williams Sink; Bone Spring
	11 County or Parish, State Eddy NM

12 CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug back	<input type="checkbox"/> Water Disposal	

13 Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Spud 6-28-12

7/2/12 TD 17 1/2" hole @ 900'. Set 13 3/8" 54.5# J-55 csg @ 900'. Cmt w/450 sx Class C. Tailed in w/450 sx. Circ 417 sx to surface. WOC 18 hrs & test to 1500#.

7/4/12 Began drlg 12 1/4" hole.

7/5/12 to 8/1/12 Drill to 3834'. Working tight hole. Drill to 3930'. Pipe stuck @ 3906'. Ran free-point & back off @ 3186'. Left 719' in hole. TOF @ 3125'. Wash over fish. Jar on fish. Retrieve 1 DC. TOF @ 3135'. Wash over fish. Screw into fish. Jar on fish. TOF @ 3155'. Ran free-point & back off. Wash over fish. TOF @ 3244'. Jar on stuck pipe. 4 jts wash pipe in hole. Top of 2nd fish @ 3184'. TIH open-ended to 3176'. Pmpd 450 sx. WOC. Tag @ 2589'. Slide drill 12 1/4" side track. Drill to 4008'. Work stuck pipe. Ran free-point. Shoot off @ 3205', leaving 796' in hole. TOF @ 3205'. Wash over fish. Run spud bar & chisel. Knock down to 3580'. Ran free-point. Top of DC @ 3245'. Wash pipe. Pipe stuck @ 3322'. Jar on pipe. TOO H w/parted wash pipe. Left 5 jts in hole. Received verbal approval from Wesley Ingram (BLM) to P&A well.

8/2/12 TIH open-ended to 3162'. Pmpd 300 sx Class C. Notified Joe Salcido (BLM) prior to pmpg plug. Tag @ 2772'. Pmpd 2nd plug @ 2620' w/175 sx Class C. Tag @ 2551'. Pmpd 3rd plug @ 2540' w/150 sx Class C. Tag @ 2430'. Witnessed by Joe Salcido.

8/3/12 Pmpd 300 sx Class C @ 1076'. WOC. Tag @ 545'. Cmt surface plug w/35 sx Class C from 50' to surface. Witnessed by Joe Valdez (BLM). Cut off 13 3/8" WH. Clean pits. Released rig.

Well is Plugged & Abandoned.

14 I hereby certify that the foregoing is true and correct

Name (Printed/ Typed)

Stormi Davis

Title

Regulatory Analyst

Date

8/20/12

Signature

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 USC Section 1001 AND Title 43 USC Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

ACCEPTED FOR RECORD

AUG 26 2012

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICEAccepted for record
NMOCD

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised August 1, 2011

WELL API NO. 30-015-38147
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> FED/INDIAN <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lizard Pot Federal Com
8. Well Number 3H
9. OGRID Number 229137
10. Pool name or Wildcat WC Williams Sink; Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	RECEIVED AUG 30 2012 NMOCD ARTESIA
2. Name of Operator COG Operating LLC	
3. Address of Operator 2208 W. Main Street, Artesia, NM 88210	

4. Well Location Unit Letter <u>J</u> : <u>1650</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>East</u> line Section <u>36</u> Township <u>19S</u> Range <u>31E</u> NMPM <u>Eddy</u> County	11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3487' GR
---	--

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/2/12 TD 17 1/2" hole @ 900'. Set 13 3/8" 54.5# J-55 csg @ 900'. Cmt w/450 sx Class C. Tailed in w/450 sx. Circ 417 sx to surface. WOC 18 hrs & test to 1500#.

7/4/12 Began drlg 12 1/4" hole.

7/5/12 to 8/1/12 Drill to 3834'. Working tight hole. Drill to 3930'. Pipe stuck @ 3906'. Ran free-point & back off @ 3186'. Left 719' in hole. TOF @ 3125'. Wash over fish. Jar on fish. Retrieve 1 DC. TOF @ 3135'. Wash over fish. Screw into fish. Jar on fish. TOF @ 3155'. Ran free-point & back off. Wash over fish. TOF @ 3244'. Jar on stuck pipe. 4 jts wash pipe in hole. Top of 2nd fish @ 3184'. TIH open-ended to 3176'. Pmpd 450 sx. WOC. Tag @ 2589'. Slide drill 12 1/4" side track. Drill to 4008'. Work stuck pipe. Ran free-point. Shoot off @ 3205', leaving 796' in hole. TOF @ 3205'. Wash over fish. Run spud bar & chisel. Knock down to 3580'. Ran free-point. Top of DC @ 3245'. Wash pipe. Pipe stuck @ 3322'. Jar on pipe. TOO H w/parted wash pipe. Left 5 jts in hole. Received verbal approval from Wesley Ingram (BLM) to P&A well.

8/2/12 TIH open-ended to 3162'. Pmpd 300 sx Class C. Notified Joe Salcido (BLM) prior to pmpg plug. Tag @ 2772'. Pmpd 2nd plug @ 2620' w/175 sx Class C. Tag @ 2551'. Pmpd 3rd plug @ 2540' w/150 sx Class C. Tag @ 2430'. Witnessed by Joe Salcido.

8/3/12 Pmpd 300 sx Class C @ 1076'. WOC. Tag @ 545'. Cmt surface plug w/35 sx Class C from 50' to surface. Witnessed by Joe Valdez (BLM). Cut off 13 3/8" WH. Clean pits. Released rig.

Well is Plugged & Abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stormi Davis TITLE: Regulatory Analyst DATE: 8/30/12
Type or print name: Stormi Davis E-mail address: sdavis@concho.com PHONE: (575) 748-6946

For State Use Only

APPROVED BY: accepted for record TITLE: _____ DATE: _____
Conditions of Approval (if any): _____