Form 3160-5 (August 2007)

Approved By EDWARD FERNANDEZ

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

UNITED STATES

FORM APPROVED OMB NO 1004-0135


Date 10/17/2012

Bi	.	July 31, 2010			
SUNDRY Do not use thi	NMNM81616	NMNM81616 ·			
abandoned wel	6 If Indian, Allottee o	6 If Indian, Allottee or Tribe Name			
SUBMIT IN TRII	7 If Unit or CA/Agree	7 If Unit or CA/Agreement, Name and/or No.			
1 Type of Well	8 Well Name and No	8 Well Name and No H B 10A FEDERAL 8			
Oil Well Gas Well Oth Name of Operator	9 API Well No				
DEVON ENERGY PRODUCT	30-015-29915-0	00-S1			
3a Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 73102		3b Phone No (include area code) Ph. 405-552-7848		10 Field and Pool, or Exploratory CEDAR CANYON	
4 Location of Well (Footage, Sec., 7	, R, M, or Survey Descriptio	n)	11. County or Parish,	11. County or Parish, and State	
Sec 10 T24S R29E SESE 660	FSL 400FEL		EDDY COUNT	EDDY COUNTY, NM	
		•			
12CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF N	OTICE, REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	-	TYPE OF	ACTION		
Notice of Intent	☐ Acidize	Deepen	Production (Start/Resume)	☐ Water Shut-Off	
Notice of Intent	☐ Alter Casing	Fracture Treat	Reclamation	☐ Well Integrity	
☐ Subsequent Report	Casing Repair	☐ New Construction	Recomplete .	Other Workover Operations	
Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon		
,	☐ Convert to Injection	□ Plug Back	□ Water Disposal		
Attach the Bond under which the wo following completion of the involved testing has been completed Final Al determined that the site is ready for f	ally or recomplete horizontally, rk will be performed or provide operations. If the operation re- pandonment Notices shall be final inspection.)	give subsurface locations and measure the Bond No on file with BLM/BIA sults in a multiple completion or recor- led only after all requirements, including	ed and true vertical depths of all perti Required subsequent reports shall b npletion in a new interval, a Form 31 ng reclamation, have been completed	nent markers and zones e filed within 30 days 60-4 shall be filed once , and the operator has	
Devon Energy Production Corproduction csg to the 8 5/8" in	mpany L P. respectfully r Itermediate csg as propo	equests approval to tie-in ceme sed in the attached procedure.	ent behind 5 1 Accepted	for record	
Please see attached workove	r proposal and wellbore s	schematic.	141414	10/21/	
	AS OF AFTRO VI	RECEIVED OCT 2 2 2012 NMOCD ARTESIA	APPROVE oct 17	2012 2012 2 MANAGENER 2 MANAGENER 2 MANAGENER 2 MANAGENER 2 MANAGENER 2 MANAGENER 2 MANAGENER 2 MANAGENER 3 MANAGE	
14 I hereby certify that the foregoing is	Electronic Submission #	147647 verified by the BLM Well GY PRODUCT ON CO LP, sent to	Information System CARLSBAU		
	nmitted to AFMSS for proc	essing by KURT SIMMONS on 0	9/07/2012 (12KMS2012SE)	•	
Name (Printed/Typed) DAVID H	соок	Title REGULA	TORY SPECIALIST		
Signature (Electronic S	Submission)	Date 08/28/20	12		
	THIS SPACE F	OR FEDERAL OR STATE C	FFICE USE		

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

TitlePETROLEUM ENGINEER

Office Carlsbad



H B 10A Fed 8 WBS

Objective - Tie- in Cement behind 5-1/2" production csg to 8-5/8" intermediate casing

API# - 30-015-29915

Location - Eddy Co.-Sec 10, 24S 29E, 660' FSL, 400' FEL

GL - 2,944 ft

KB - (13')

TD - 8,214 ft

PBTD - 8,174 ft

Casing	OD	#s/FT	Grade	Тор	Bottom	тос	80% Collapse (psi)	80% Burst (psi)
Surface	13-3/8"	48.00#	H-40	0'	350'	0'	,	
Intermediate	8-5/8"	24.00#	K-55	0,	2,933'	0'		2,360
		15.5#	K-55	0' -	6,030'			<u> </u>
Production	5-1/2"	17#	K-55	6,03 0' -	8,214'	Est. 3,210'	3,232	3,848
Production								·—
Tubing	2-7/8"	6.4#	N-80	0'	7,408'		8,928	8,456
	a .							

Capacity 2-7/8" tbg - 0.00579 bbl/ft

Current Rods and Pump (Top down): 2 - 1" rod subs (?'), 79 - 1" rods, 88 - 7/8" rods, 139 - 34" rods, 10 - 1" rods, 2' rod lift sub (?") and 2-1/2" X 1-1/4" X 20 X 22 RHBCHVRTS Pump.

Current TBG (Top down): 216 jts - 2-7/8", 6.5#, (grade?) tbg (6,767'), 2-7/8" x 5-1/2" TAC w/45K shear (3'), 36 jts - 2-7/8", 6.5# (grade?) tbg (1,124'), 1 - 2-7/8" blast nipple (6'), 1 - 2-7/8" SN (1'), 1 - 2-7/8" perforated sub (4') and 1 - 2-7/8" bull plugged Mud anchor (31.90') TAC @ 6,782'; SN @ 7,912'; EOT @ 7,949'

Current perforations

Bone Spring (Avalon - 2003)

6,871' - 6,891' (20' - 40 holes)

Bone Spring (1998)


7,829' - 7,934' (5' - 6 holes)

7,844' - 7,949' (5' - 6 holes)

7,922' - 7,929' (7' - 8 holes)

Safety:


All personnel will wear hard hats, safety glasses with side shields, and steel toed boots while on location. Assess wellhead working height for safety. If needed, use work platform or man-lift for fall protection. H2S monitoring equipment is required by BLM to be on location.



H B 10A Fed 8

Procedure


- 1) Test anchors. Hot water tubing & rods 2-3 days prior to rig moving in.
- 2) Notify appropriate regulatory agencies prior to starting work.
- 3) MIRU WSU. NU rod rams. Unseat pump & TOH w/ rods & pump. ***Note grade & # of rods. Input into Wellview.
- 4) ND rod rams. NU BOPE. Test BOPE to Devon guidelines.
- 5) Unseat TAC. TOH w/ 2-7/8" tubing & BHA. ***Note number of joints of tubing and grade. If tubing or rods still look to have paraffin, make bit & scraper run.
- 6) TIH w/ 5-1/2", 15.5# RBP and 2-7/8" tbg to 4,100' and set RBP. Circ, load and balance hole w/ 2% KCL. Test RBP & 5-1/2" casing to 1,500 psi for 30 min. If ok, dump 4 cu ft sand (~30') of sand on top of RBP. TOH w/ 2-7/8" tbg.
- 7) RU WL w/packoff. Run GR-CCL-CBL from 4,000' to 2,000'. Confirm TOC w/OKC engineering before proceeding.
- 8) RU WL w/ full lubricator. Test lubricator to Devon guidelines. TIH w/ a 1' 3-1/8" perf gun loaded 4 spf (90 degree phasing) and shoot squeeze holes ABOVE TOP OF CEMENT.
- 9) Open 8-5/8" Intermediate casing valves. Pump 2% KCL down 5-1/2" casing in attempt to circulation between 5-1/2" by 8-5/8" csgs through squeeze holes. Do not exceed 1,500 psi at surface down casing. If unsuccessful, contact OKC engineering to discuss next option(s) with a 5-1/2" packer. If ok proceed.
- 10) TIH with 5-1/2", (15.5# to 17#) cement retainer and 2-7/8" tbg to~ 50' above squeeze holes and set retainer (hydro test 2-7/8" tubing to 8,000 psi below slips while TIH).
- 11) Sting in and out of cement retainer to make sure it is working properly.
- 12) RU pumping services. Test lines. Sting into cement retainer. Pump 2% KCL to determine if circulation can be achieved (below retainer) into squeeze perfs (top pressure 1,500 psi at surface). If circ is achieved, pump @ minimum ~ 100 bbls of 2% KCL once circulation is established. Sting out of retainer.



H B 10A Fed 8

Procedure cont.

- 13) RU BHI cementing services (proposal # 690851024B) or equivalent. Test lines. Sting into retainer.
 - a. Establish circ & pump 20 bbls fresh water ahead
 - b. Mix & pump ~ 375 sks 60:40 Poz Class C cement (catch surface samples of cmt).
 - c. Flush 2-7/8" tbg w/ fresh water. Leave at minimum, 1 bbl cement in tbg prior to stinging out of retainer.
 - d. Sting out of retainer and pick up 2-7/8" tbg 2' and reverse circ clean with a minimum 1-1/2 time tubing capacity with 2% KCL or until clean. Report any/all cement returns volumes noted.
 - e. TOH with 2-7/8" tbg and cement stinging tool (remove stinging tool)
 - f. RD BHI or equivalent cementing services
 - g. Run kill string and SWI a minimum of 24 hrs (check surface samples for hardness)
- 14) RU WL w/ packoff. Run GR-CCL-CBL Log from top of retainer to 200' above TOC. If Cement is not tied back to the Intermediate casing contact OKC engineering. If ok, proceed.
- 15) TIH with 4-3/4" bit, bit sub, (4-6) 3-1/2" drill collars, x/o and 2-7/8". Drill out cement retainer and cement. Drop down and wash out \sim 10' of sand and circulate clean.
- 16) Test 5-1/2" casing and squeeze holes to 1,000 psi. If ok, proceed. If not, contact OKC (engineering.
- 17) TOH and lay down drill collars & bit.
- 18) TIH w/ RBP retrieving tool. Wash out remaining ~ 20' sand and circulate RBP clean.
- 19) Retrieve RBP and TOH with 2-7/8" tbg and RBP.
- 20) TIH w/ original BHA and rod design. Test downhole pump.
- 21) RDMO WSU and return all rentals.
- 22) Turn well over to production.



Conditions of Approval

Sundry dated 08/28/2012 H B 10A Federal #8 30-015-29915 Devon Energy Production

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Closed loop system required.
- 3. 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 4. Step 9 of operator's proposal Also contact BLM if unsuccessful
- 5. Step 14 of operator's proposal Also contact BLM if cement does not tie back.
- 6. Step 16 of operator's proposal as stated Pressure test casing to 1,000 psi. Hold for 15min on a chart recorder and submit Chart recorder to BLM
- 7. Operator to submit copy of CBL before cement work is done and a copy of CBL after work is done.
- 8. Work to be completed in 90 days
- 9. Subsequent sundry describing work done required

EGF 101712