

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

WELL API NO.	30-015-33476
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	VO-6442
7. Lease Name or Unit Agreement Name	ZONKED STATE
8. Well Number	1
9. OGRID Number	14049
10. Pool name or Wildcat	CEMETERY; MORROW, SE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
MARBOB ENERGY CORPORATION

3. Address of Operator
PO BOX 227, ARTESIA, NM 88211-0227

4. Well Location

Unit Letter N : 660 feet from the SOUTH line and 1650 feet from the WEST line

Section 2 Township 21S Range 24E NMPM County EDDY

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3863' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ADD ADD'L PAY ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MARBOB ENERGY CORPORATION PROPOSES TO ADD ADDITIONAL PAY IN THE
MORROW SANDS AS FOLLOWS:

PERF THE MIDDLE MORROW @ 9919' - 10013' (120 SHOTS). FLOW/SWAB TEST.
ACIDIZE W/ 1000 GAL CLAY SAFE H ACID. SWAB/FLOW TEST. WHEN READY TO
TEST UPPER MORROW, PLUG BACK TECHNIQUE WILL BE DETERMINED BASED ON
RESULTS OF PREVOIUS ZONE(S). PERF THE UPPER MORROW @ 9836' - 9846'
(54 SHOTS). FLOW/SWAB TEST. ACIDIZE W/ 500 GAL CLAY SAFE H ACID.
SWAB/FLOW TEST.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diana J. Briggs TITLE PRODUCTION ANALYST DATE 5/13/05

Type or print name DIANA J. BRIGGS

Telephone No. (505) 748-3303

(This space for State use)

TIM W. GUM

APPROVED BY DISTRICT IV SUPERVISOR TITLE

MAY 24 2005

DATE

Conditions of approval, if any: